



# Aviation Investigation Final Report

---

<b>Location:</b>	Apopka, Florida	<b>Accident Number:</b>	ERA16LA213
<b>Date &amp; Time:</b>	June 10, 2016, 16:10 Local	<b>Registration:</b>	N8943Z
<b>Aircraft:</b>	Cessna 310	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Miscellaneous/other	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Flight test		

---

## Analysis

The airline transport pilot reported that the accident flight was the airplane's first flight following completion of an annual inspection. He added that there were no issues with the brakes while taxiing to fuel the airplane or to depart. After performing two touch-and-go landings and a go-around, the pilot approached the runway intending to conduct a full-stop landing. He stated that the airplane touched down at the normal point/location and that he then retracted the flaps during the landing roll but waited to apply brakes until the airplane approached the end of the runway. Upon applying the brakes, the left brake did not work, but the right brake did, which resulted in the airplane drifting right. The pilot realized that the airplane was going to exit the right side of the runway, so he secured the engines and attempted to maintain control while applying right braking in an effort to slow the airplane. The airplane travelled off the right side of the runway and impacted upsloping terrain.

Initial postaccident operational testing of the brakes revealed no discrepancies with the left brake. No brake system leaks were noted, and the fluid levels in both brake master cylinders were at correct levels. However, during subsequent operational testing of the left brake master cylinder, the left brake worked satisfactorily once but failed during subsequent testing.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The intermittent failure of the left brake master cylinder, which resulted in asymmetric braking and the subsequent loss of directional control during the landing roll.

## Findings

---

<b>Aircraft</b>	Master cylinder/brake valve - Damaged/degraded
<b>Aircraft</b>	Master cylinder/brake valve - Failure
<b>Aircraft</b>	Directional control - Attain/maintain not possible

## Factual Information

### History of Flight

<b>Landing-landing roll</b>	Miscellaneous/other (Defining event)
<b>Landing-landing roll</b>	Abrupt maneuver
<b>Landing-landing roll</b>	Loss of control on ground
<b>Landing-landing roll</b>	Runway excursion
<b>Landing-landing roll</b>	Collision with terr/obj (non-CFIT)

On June 10, 2016, about 1610 eastern daylight time, a Cessna 310G, N8943Z, collided with a berm while landing at Orlando Apopka Airport (X04), Apopka, Florida. The airline transport pilot was not injured, and the airplane was substantially damaged. The airplane was registered to SOFI, LLC, and was operated by a private individual under the provisions of 14 Code of Federal Regulations as a Part 91 local, post maintenance test flight. Visual meteorological conditions prevailed and no flight plan was filed for the flight that departed from X04 at 1515.

The accident flight was the airplane's first flight after an annual inspection. Prior to that flight, it had not been operated in the previous 2 years.

The pilot stated that after release from the inspection, he performed a preflight inspection and noticed several discrepancies, none of which were related to the aircraft's brake system. After the airplane was removed from the hangar, he started the engines and taxied to a place where he fueled the airplane, and during the taxi, he did not indicate any issues with the aircraft's brakes. Following fueling he taxied to runway 33, a 3,987-foot-long asphalt runway where he initiated takeoff and remained in the traffic pattern performing two touch-and-go landings to the same runway.

After the second touch-and-go landing, he remained in the traffic pattern and intended to perform a full-stop landing; however, he had to initiate a go-around because another airplane was on the runway. He returned and reported the touchdown was normal and in the normal/typical location. After touchdown he retracted the flaps and allowed the airplane to slow aerodynamically to the end of the runway. As the airplane approached the end of the runway, the pilot applied the normal brakes; however, the left brake did not function. The airplane started drifting to the right, and as the airplane slowed to a slow taxi speed, the right deviation became more pronounced and he pumped the left brake and applied pressure but it seemed the left brake pedal went to the floor with no pressure or effect. When it became evidence that the airplane would depart the runway he secured the engines, and attempted to maintain control while applying the right brake in an effort to slow the airplane. The airplane went off the right side of the runway at the end and contacted upsloping terrain which caused spar damage to the left horizontal stabilizer.

Operational testing of the pilot's side brakes by a Federal Aviation Administration (FAA) operations inspector following recovery revealed no discrepancies; however, operational testing of the brakes on the copilot's side revealed a discrepancy with the right brake. No brake system leaks were noted and the

fluid levels in both brake master cylinders were at the correct level. The airplane was retained for further examination.

Further examination of each brake master cylinder was performed by an FAA airworthiness inspector. Following removal from the airplane, the left brake worked once but on the second actuation, the actuating rod slowly leaked internally to the bottom. The right brake worked perfectly when removed. Both cylinders had an acceptable fluid level after removal. Disassembly of the brake master cylinders revealed all o-rings were in a reasonable condition with no visible cuts or tears. The left brake had a dark crusty compound and a small washer in the reservoir, while the right brake had the same compound including the washer, but was not as contaminated as the left. It was not possible to determine part numbers or serial numbers of either brake master cylinder as the data plates were damaged by hydraulic fluid.

According to the facility that performed the inspection, they utilized a generic twin-engine checklist to perform the inspection. The owner/general manager of the facility where the inspection was performed stated there were no discrepancies related to the brakes during the engine run-ups prior to the inspection.

### Pilot Information

<b>Certificate:</b>	Airline transport; Flight instructor	<b>Age:</b>	59, Male
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 1 With waivers/limitations	<b>Last FAA Medical Exam:</b>	May 18, 2016
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	November 28, 2015
<b>Flight Time:</b>	28000 hours (Total, all aircraft), 500 hours (Total, this make and model), 25500 hours (Pilot In Command, all aircraft), 150 hours (Last 90 days, all aircraft), 0 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N8943Z
<b>Model/Series:</b>	310 G	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1962	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	310G-0043
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	6
<b>Date/Type of Last Inspection:</b>	June 10, 2016 Annual	<b>Certified Max Gross Wt.:</b>	4990 lbs
<b>Time Since Last Inspection:</b>	1 Hrs	<b>Engines:</b>	2 Reciprocating
<b>Airframe Total Time:</b>	as of last inspection	<b>Engine Manufacturer:</b>	CONT MOTOR
<b>ELT:</b>	Installed	<b>Engine Model/Series:</b>	IO-470-D
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	260 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	LEE,76 ft msl	<b>Distance from Accident Site:</b>	14 Nautical Miles
<b>Observation Time:</b>	15:53 Local	<b>Direction from Accident Site:</b>	300°
<b>Lowest Cloud Condition:</b>	Scattered / 6000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>		<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	10 knots /	<b>Turbulence Type Forecast/Actual:</b>	/ None
<b>Wind Direction:</b>	50°	<b>Turbulence Severity Forecast/Actual:</b>	/ N/A
<b>Altimeter Setting:</b>	30.04 inches Hg	<b>Temperature/Dew Point:</b>	34°C / 21°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Apopka, FL (X04 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Apopka, FL (X04 )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	15:15 Local	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Orlando Apopka Airport X04	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	150 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	33	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3987 ft / 60 ft	<b>VFR Approach/Landing:</b>	Full stop;Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	28.712223,-81.584999

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Monville, Timothy
<b>Additional Participating Persons:</b>	Larry Enlow; FAA/FSDO; Orlando, FL Terry E Jones; FAA/FSDO; Orlando, FL
<b>Original Publish Date:</b>	October 17, 2017
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=93375">https://data.ntsb.gov/Docket?ProjectID=93375</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).