



Aviation Investigation Final Report

Location: Greers Ferry, Arkansas **Accident Number**: GAA16CA310

Date & Time: June 12, 2016, 08:35 Local Registration: N1244L

Aircraft: CONSOLIDATED AERONAUTICS INC. LAKE LA 4 Aircraft Damage: Substantial

Defining Event: Abnormal runway contact **Injuries:** 2 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the amphibious airplane reported that during the 4th water landing of the flight, during touchdown, "the nose pitched down aggressively" and the airplane nosed over. The pilot further reported that he and the passenger were able to perform an emergency evacuation before the airplane sank. The fuselage sustained substantial damage.

During a postaccident interview with the National Transportation Safety Board investigator-in-charge, the pilot reported that boat wake developed in the landing area and the nose of the airplane "may have been a little low" during the landing.

According to a police report, the passenger reported that "we misjudged the wave and the plane flipped onto its back."

The pilot did not report any mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The amphibious airplane pilot's incorrect pitch attitude during landing on choppy water, which resulted in a nose over, and substantial damage to the fuselage.

Findings

Aircraft Pitch control - Incorrect use/operation

Personnel issues Aircraft control - Pilot

Environmental issues Choppy surface - Contributed to outcome

Page 2 of 6 GAA16CA310

Factual Information

History of Flight

Landing-flare/touchdown	Abnormal runway contact (Defining event)
Landing-flare/touchdown	Loss of control on ground
Landing-flare/touchdown	Nose over/nose down

Pilot Information

Certificate:	Airline transport; Flight instructor	Age:	65,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	April 1, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 3, 2015
Flight Time:	(Estimated) 28000 hours (Total, all aircraft), 80 hours (Total, this make and model), 23000 hours (Pilot In Command, all aircraft), 100 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 9 hours (Last 24 hours, all aircraft)		

Passenger Information

Certificate:		Age:	16,Male
Airplane Rating(s):		Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	Unknown
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Page 3 of 6 GAA16CA310

Aircraft and Owner/Operator Information

Aircraft Make:	CONSOLIDATED AERONAUTICS INC.	Registration:	N1244L
Model/Series:	LAKE LA 4 200	Aircraft Category:	Airplane
Year of Manufacture:	1976	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	743
Landing Gear Type:	Tricycle; Amphibian; Hull	Seats:	4
Date/Type of Last Inspection:	August 1, 2015 Annual	Certified Max Gross Wt.:	2600 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1600 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91 installed	Engine Model/Series:	IO-360-A1B
Registered Owner:	On file	Rated Power:	200 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCCA,513 ft msl	Distance from Accident Site:	13 Nautical Miles
Observation Time:	13:35 Local	Direction from Accident Site:	270°
Lowest Cloud Condition:	Clear	Visibility	9 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/ None
Wind Direction:		Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.11 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	HIGDEN, AR (06AR)	Type of Flight Plan Filed:	VFR
Destination:	HIGDEN, AR (06AR)	Type of Clearance:	None
Departure Time:	08:00 Local	Type of Airspace:	Class G

Page 4 of 6 GAA16CA310

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	35.525833,-92.166664(est)

Page 5 of 6 GAA16CA310

Administrative Information

Investigator In Charge (IIC):	Gerhardt, Adam
Additional Participating Persons:	Mike W Minnex; FAA; Little Rock, AR
Original Publish Date:	August 31, 2016
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=93377

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 GAA16CA310