



Aviation Investigation Final Report

Location: Port St. Lucie, Florida Accident Number: GAA16CA510

Date & Time: September 16, 2016, 19:00 Local Registration: N3771F

Aircraft: Great Lakes 2T1A Aircraft Damage: Substantial

Defining Event: Miscellaneous/other **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tandem-seat, tailwheel equipped biplane reported that he was flying from the rear seat which limits his forward view, "especially in the landing configuration". He further reported that during the landing roll on a private grass airstrip, the biplane impacted a drainage pipe, which resulted in a collapsed left landing gear and substantial damage to both lower wings and the lower right aileron.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to avoid the drainage pipe during the landing roll on a private grass airstrip. Contributing to the accident was the pilot's reduced forward view from the rear seat.

Findings

Personnel issues	Monitoring environment - Pilot
Environmental issues	Visibility - Effect on personnel
Environmental issues	(general) - Effect on operation

Factual Information

History of Flight

Landing-landing roll	Miscellaneous/other (Defining event)	

Pilot Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	66,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Unknown
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane; Instrument helicopter	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	August 9, 2016
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	June 30, 2016
Flight Time:	(Estimated) 14500 hours (Total, all aircraft), 65 hours (Total, this make and model), 14300 hours (Pilot In Command, all aircraft), 85 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 2 of 5 GAA16CA510

Aircraft and Owner/Operator Information

Aircraft Make:	Great Lakes	Registration:	N3771F
Model/Series:	2T1A 2	Aircraft Category:	Airplane
Year of Manufacture:	1977	Amateur Built:	
Airworthiness Certificate:	Aerobatic	Serial Number:	0764
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	June 10, 2016 Annual	Certified Max Gross Wt.:	1800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	678 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	AEIO-360-B1G6
Registered Owner:	On file	Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Vieual (VMC)	Condition of Lights	Dov
Conditions at Accident Site.	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSUA,18 ft msl	Distance from Accident Site:	15 Nautical Miles
Observation Time:	22:47 Local	Direction from Accident Site:	104°
Lowest Cloud Condition:	Scattered / 5500 ft AGL	Visibility	7 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	3 knots / None	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	29°C / 25°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	FORT LAUDERDALE, FL (FXE)	Type of Flight Plan Filed:	None
Destination:	Port St. Lucie, FL (FL37)	Type of Clearance:	None
Departure Time:	18:00 Local	Type of Airspace:	Class G

Page 3 of 5 GAA16CA510

Airport Information

Airport:	TREASURE COAST AIRPARK FL37	Runway Surface Type:	Grass/turf
Airport Elevation:	30 ft msl	Runway Surface Condition:	Dry
Runway Used:	09	IFR Approach:	None
Runway Length/Width:	4000 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	27.240833,-80.488334(est)

Page 4 of 5 GAA16CA510

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Cheryl King; FAA; Orlando, FL
Original Publish Date:	December 15, 2016
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=94080

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 GAA16CA510