



Aviation Investigation Final Report

Location: Arcadia, Florida Accident Number: GAA17CA040

Date & Time: October 23, 2016, 15:00 Local Registration: N7329K

Aircraft: Piper PA 20S Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Ferry

Analysis

The pilot reported that he ferried the straight float-equipped airplane to a grass airstrip for an annual inspection. During landing on the grass airstrip in crosswind conditions, the pilot reported that upon touchdown he applied back pressure to the controls and added power, but the airplane lifted and came back down quickly. The crosswind had drifted the airplane to the left and as the airplane began to slow on the runway the pilot felt the left float buckle. Subsequently, the left wing and nose impacted the ground and the airplane nosed over, coming to rest inverted.

The airplane sustained substantial damage to both wings, the fuselage, and the rudder.

The pilot reported that there were no pre impact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

The pilot reported the wind as 060 degrees true at 10 nautical miles per hour, and not gusting. The pilot landed on runway 31.

The pilot reported that the grass had just been cut, and that it would have been better if there had been dew on the grass. He further reported that the crosswind drifted the airplane to the left causing the left float to collapse. He wrote that he should have returned home and come back the following day when there was dew on the grass and no headwind.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper pitch and power control during landing in a straight float-equipped airplane on grass in crosswind conditions, which resulted in a loss of directional control.

Findings

Aircraft Pitch control - Not attained/maintained

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues (general) - Effect on operation
Environmental issues (general) - Effect on operation

Page 2 of 6 GAA17CA040

Factual Information

History of Flight

Landing	Hard landing
Landing	Loss of control in flight (Defining event)
Landing	Abnormal runway contact
Landing	Dragged wing/rotor/float/other
Landing	Nose over/nose down

Pilot Information

Certificate:	Private	Age:	48,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	August 7, 2015
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 30, 2015
Flight Time:	(Estimated) 675 hours (Total, all aircraft), 300 hours (Total, this make and model), 675 hours (Pilot In Command, all aircraft)		

Page 3 of 6 GAA17CA040

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N7329K
Model/Series:	PA 20S UNDESIGNAT	Aircraft Category:	Airplane
Year of Manufacture:	1950	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	20-236
Landing Gear Type:	Float	Seats:	4
Date/Type of Last Inspection:	September 30, 2015 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2500 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-320
Registered Owner:	On file	Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PGD,30 ft msl	Distance from Accident Site:	18 Nautical Miles
Observation Time:	18:53 Local	Direction from Accident Site:	204°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.14 inches Hg	Temperature/Dew Point:	27°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Manatee River, FL	Type of Flight Plan Filed:	None
Destination:	Arcadia, FL (X06)	Type of Clearance:	None
Departure Time:	14:00 Local	Type of Airspace:	Class G

Page 4 of 6 GAA17CA040

Airport Information

Airport:	ARCADIA MUNI X06	Runway Surface Type:	Grass/turf
Airport Elevation:	63 ft msl	Runway Surface Condition:	Dry
Runway Used:	31	IFR Approach:	None
Runway Length/Width:	2780 ft / 140 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	27.195554,-81.840278(est)

Page 5 of 6 GAA17CA040

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Robert R Blake; FAA; Tampa, FL
Original Publish Date:	December 15, 2016
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=94273

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 GAA17CA040