



# Aviation Investigation Final Report

<b>Location:</b>	Royalton, Wisconsin	<b>Accident Number:</b>	CEN17LA037
<b>Date &amp; Time:</b>	November 6, 2016, 16:00 Local	<b>Registration:</b>	N801KJ
<b>Aircraft:</b>	JOHNSON KENNETH R STOL CH 801	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>	Loss of control in flight	<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The purpose of the personal flight was to practice stalls in the homebuilt, experimental airplane. The private pilot reported that he practiced several stall maneuvers and that the airplane handled well. After executing a touch-and-go landing, the pilot took off and established the airplane on downwind, about 1,000 ft above ground level, to set up for a full flaps landing. He lowered the flaps and set the engine power to idle. The pilot then discovered that the control stick would move but that he had no control of the airplane. The airplane impacted the ground and was totally consumed by postimpact fire. The pilot did not remember the crash. He had flown the airplane the day before the accident and did not report any mechanical anomalies. The pilot indicated that he did not believe that the airplane stalled. Due to the extent of the postimpact fire damage, it was not possible to determine any preimpact malfunctions or failures of the engine, flight controls, or flight control surfaces. Thus, the reason for the loss of control could not be determined.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of control during approach for reasons that could not be determined due to postimpact fire damage.

### Findings

<b>Not determined</b>	(general) - Unknown/Not determined
-----------------------	------------------------------------



## Factual Information

### History of Flight

<b>Approach-VFR pattern downwind</b>	Loss of control in flight (Defining event)
<b>Uncontrolled descent</b>	Collision with terr/obj (non-CFIT)
<b>Post-impact</b>	Fire/smoke (post-impact)

On November 6, 2016, about 1600 central daylight time, an Zenith 801 homebuilt, experimental airplane, N801KJ, registered to the pilot, was destroyed by a postimpact fire after it impacted the ground while on approach to Runway 18 at the Northport Airport (WI38), Royalton, Wisconsin. The private pilot, who was the sole occupant, sustained minor injuries. The local personal flight was being conducted under the provisions of Federal Code of Regulations Part 91. Visual meteorological conditions prevailed throughout the area and a flight plan was not filed. The flight originated about 1530 from WI38.

The pilot reported that he had built the airplane over the last 14 years. The airplane was approved for a 40-hour testing period on May 12, 2016, when it received its continuous airworthiness inspection. The airplane was flown by the pilot on the day prior to the accident and he reported no mechanical anomalies.

The pilot provided a detailed account of the day's flight and accident on NTSB Form 6120. He reported that the purpose of the flight was to practice stalls and how the airplane responded. On the first flight of the day, the airplane stalled with full power at 38-39 mph, neither wing stalled first, and the flight was straight and stable. He landed with full flaps on the grass runway, and took off for more testing. He then performed a successful full-flap engine idle stall. The airplane stalled at 28-29 mph, both wings stayed level, and the airplane flew straight. He performed a touch and go landing, took off, and established the airplane on downwind, about 1,000 feet AGL, to set up for a full flap landing. He lowered the flaps and set the engine power to idle. The pilot discovered that the control stick would move, but he had no control of the airplane. The stick would move, but the airplane could not be controlled. The airplane impacted the ground and the pilot did not remember the crash. Neighbors helped to evacuate the pilot from the wreckage and local responders transported the pilot to a hospital. There were no eye-witnesses to the accident, however, a neighbor reported hearing the airplane and thought that he heard the engine backfire.

The airplane was totally consumed by a post-impact fire. An FAA inspector examined the wreckage, but due to the extent of fire damage, it was not possible to determine any pre-impact anomalies with the engine, flight controls, or flight control surfaces. The pilot reported that he did not believe that the airplane stalled.

The pilot also stated on NTSB Form 6120, that the 5-point harness that he installed on his homebuilt airplane probably saved his life.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	65, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	April 12, 2016
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	August 1, 2016
<b>Flight Time:</b>	(Estimated) 100 hours (Total, all aircraft), 13 hours (Total, this make and model), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	JOHNSON KENNETH R	<b>Registration:</b>	N801KJ
<b>Model/Series:</b>	STOL CH 801 NO SERIES	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental light sport (Special)	<b>Serial Number:</b>	8-4899
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	May 1, 2016 Condition	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>	13 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	13 Hrs at time of accident	<b>Engine Manufacturer:</b>	Mazda Rotary
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	100 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>		<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>		<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	5 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	180°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.92 inches Hg	<b>Temperature/Dew Point:</b>	20°C / 16°C
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Royalton, WI (38WI)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Royalton, WI (38WI)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	15:30 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	Northport Airport 38WI	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	800 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	On-ground
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor	<b>Latitude, Longitude:</b>	44.383335,-88.8525(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Lemishko, Alexander
<b>Additional Participating Persons:</b>	Tim Spreen; FAA FSDO; Milwaukee, WI
<b>Original Publish Date:</b>	June 25, 2019
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=94346">https://data.ntsb.gov/Docket?ProjectID=94346</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).