



# Aviation Investigation Final Report

---

<b>Location:</b>	Blairstown, New Jersey	<b>Accident Number:</b>	ERA17LA042
<b>Date &amp; Time:</b>	November 10, 2016, 09:15 Local	<b>Registration:</b>	N8849H
<b>Aircraft:</b>	North American Navion	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of control on ground	<b>Injuries:</b>	1 Fatal
<b>Flight Conducted Under:</b>	Part 91: General aviation - Ferry		

---

## Analysis

The private pilot had not flown the accident airplane for almost 1 year while it underwent repairs following a gear-up landing. The purpose of the accident flight was to ferry the airplane to a nearby airport to receive an annual inspection after completion of the repairs. On the morning of the accident, a mechanic taxied the airplane and performed an engine run-up; he did not note any anomalies. The pilot fueled the airplane and started the engine for the flight. Upon starting, the engine went immediately to full power, where it remained as the airplane taxied at high speed about 1,000 ft into a tree. Witnesses reported that the pilot was awake and alert after the accident; thus, there was no evidence of pilot incapacitation. Examination of the wreckage did not reveal any preimpact mechanical malfunctions or anomalies. Based on the positions of the throttle and mixture control, and the high speed taxi after engine start, it is likely that the pilot started the engine with the throttle lever accidentally in the full-forward position. After the engine started, the pilot could have reduced or ceased engine power by retracting the throttle, retracting the mixture, or turning the magnetos off.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's improper engine start procedure, which resulted in a loss of control on the ground and collision with a tree.

## Findings

---

<b>Personnel issues</b>	Aircraft control - Pilot
<b>Personnel issues</b>	Use of equip/system - Pilot
<b>Personnel issues</b>	Incorrect action selection - Pilot
<b>Aircraft</b>	Powerplant parameters - Incorrect use/operation
<b>Aircraft</b>	Surface speed/braking - Not attained/maintained

## Factual Information

### History of Flight

<b>Standing-engine(s) start-up</b>	Loss of control on ground (Defining event)
<b>Taxi</b>	Collision with terr/obj (non-CFIT)

On November 10, 2016, about 0915 eastern standard time, a North American Navion, N8849H, was substantially damaged following a loss of control during engine startup at Blairstown Airport (1N7), Blairstown, New Jersey. The private pilot was fatally injured. The airplane was operated by the pilot under the provisions of Title 14 *Code of Federal Regulations* Part 91. Visual meteorological conditions prevailed and no flight plan was filed for the planned personal flight to Capital City Airport (CXY), Harrisburg, Pennsylvania.

According to a mechanic who witnessed the accident, the pilot, who was the owner of the airplane, last flew the accident airplane in December 2015; it was damaged during a gear-up landing at 1N7. The airplane remained at the airport while the mechanic repaired the damage. The repairs were completed, and another pilot had planned to ferry the airplane to CXY for an annual inspection the day before the accident, but the flight was postponed due to poor weather. The other pilot was not available on the day of the accident, and the owner elected to fly the airplane to CXY himself.

On the morning of the accident, the mechanic taxied the airplane from the hangar to the fuel pump. During the taxi, he performed an engine run-up and did not notice any anomalies. The mechanic added that he had performed several run-ups while the airplane was at 1N7 and never experienced any anomalies with the throttle control or brakes. After fueling the airplane and completing a preflight inspection, the pilot started the engine and it went immediately to full power. The engine remained at full power and the airplane taxied about 1,000 ft at high speed into a tree.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	73, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	January 30, 2016
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	July 16, 2015
<b>Flight Time:</b>	1478 hours (Total, all aircraft), 422 hours (Total, this make and model), 0 hours (Last 90 days, all aircraft), 0 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

The pilot, age 73, held a private pilot certificate with a rating for airplane single-engine land. His

most recent Federal Aviation Administration (FAA) third-class medical certificate was issued on January 30, 2016. At that time, he reported a total flight experience of 1,445 hours. The most recent entry in the pilot's logbook was dated February 1, 2016. According to the logbook, the pilot had accrued a total flight experience of about 1,478 hours. The pilot reported 422 hours in the accident airplane make and model on his most recent insurance application.

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	North American	<b>Registration:</b>	N8849H
<b>Model/Series:</b>	Navion UNDESIGNAT	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1947	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	NAV-4-849
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	August 21, 2015 Annual	<b>Certified Max Gross Wt.:</b>	2850 lbs
<b>Time Since Last Inspection:</b>	14 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2066 Hrs at time of accident	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	C91A installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	IO-520-BB
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	285 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

The four-seat, low-wing, retractable tricycle-gear airplane was manufactured in 1947. It was powered by a Continental IO-520, 285-horsepower engine, equipped with a constant-speed Hartzell propeller. The pilot purchased the airplane in 2009. Its most recent annual inspection was completed on August 21, 2015. At that time, the airframe had accumulated about 2,052 total hours of operation and the engine had accumulated about 417 hours since major overhaul. The airplane had been operated for about 14 hours between the time of the last inspection and the accident.

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	MPO, 1915 ft msl	<b>Distance from Accident Site:</b>	15 Nautical Miles
<b>Observation Time:</b>	08:53 Local	<b>Direction from Accident Site:</b>	305°
<b>Lowest Cloud Condition:</b>	Few / 1200 ft AGL	<b>Visibility:</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	10 knots /	<b>Turbulence Type Forecast/Actual:</b>	/ None
<b>Wind Direction:</b>	310°	<b>Turbulence Severity Forecast/Actual:</b>	/ N/A
<b>Altimeter Setting:</b>	30.02 inches Hg	<b>Temperature/Dew Point:</b>	3°C / -1°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Blairstown, NJ (1N7)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Harrisburg, PA (CXY)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>		<b>Type of Airspace:</b>	

Pocono Mountains Municipal Airport (MPO), Mount Pocono, Pennsylvania, was located about 15 miles northwest of the accident site. The 0853 recorded weather at MPO included wind from 310°; at 10 knots; visibility 10 miles; few clouds at 1,200 ft; temperature 3°C; dew point -1°C; altimeter 30.02 inches Hg.

## Airport Information

<b>Airport:</b>	Blairstown 1N7	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	371 ft msl	<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Fatal	<b>Latitude, Longitude:</b>	40.971111,-74.997497(est)

Examination of the wreckage by an FAA inspector revealed substantial damage to the wings and fuselage. The inspector noted that the throttle, propeller, and mixture controls were all in the full-forward position. Additionally, the engine had separated forward of the airframe during the collision with the tree.

The wreckage was examined again by an NTSB investigator after recovery. The propeller remained attached to the crankshaft and all three blades exhibited rotational signatures, such as torn blade tips, chordwise scrapes, and leading edge gouges. The throttle body/fuel metering unit was separated from the engine and remained attached to the induction system inlet and wye plenum, which were also separated from the airplane. The throttle and mixture control levers were fractured and their respective shafts were bent. The fractured control lever ends remained attached to the control cable rod ends. Examination of the throttle body/fuel metering unit revealed that the throttle lever was loose on the throttle control shaft; however, it was displaced and bent. No preaccident anomalies were noted with the unit.

The airplane was equipped with push-button Vernier throttle, mixture, and propeller controls. The propeller control knob was fractured and its cable was cut. Examination of the throttle control knob in the cockpit revealed that it was stuck in the full forward position and could not be pulled aft by depressing the push-button release. Examination of the mixture control revealed that it was also in the full forward position. Manual manipulation of the mixture control (both the push-button rapid adjustment mode, and the rotational fine adjustment mode) resulted in normal movement of the control knob with no anomalies noted. The throttle and mixture control knobs and cables were removed from the airplane and forwarded to the NTSB Materials Laboratory, Washington, DC.

Computed Tomography (CT) scanning of the throttle and mixture controls revealed that the outer sleeve within the throttle control did not appear to be fully seated within the knob, consistent with the throttle cable being pulled forward during engine separation in the accident sequence (for more information, see Computed Tomography Specialist's Factual Report in the public docket for this investigation).

## **Medical and Pathological Information**

---

The Morris County Medical Examiner, Morristown, New Jersey, performed an autopsy on the pilot. The autopsy report noted the cause of death as "multiple injuries."

Toxicological testing was performed on the pilot by the FAA Bioaeronautical Sciences Research Laboratory, Oklahoma City, Oklahoma. Review of the toxicology report revealed:

5.172 (ug/ml, ug/g) Ketamine detected in Urine  
2.634 (ug/ml, ug/g) Ketamine detected in Blood (Cavity)  
1.834 (ug/mL, ug/g) Norketamine detected in Urine  
0.736 (ug/mL, ug/g) Norketamine detected in Blood (Cavity)  
Midazolam detected in Blood (Cavity)  
Naproxen detected in Urine

Katamine, Norketamin, and Midazolam were consistent with emergency medical treatment that the pilot received after the accident. Naproxen is a non-sedating analgesic and not considered impairing. Additionally, according to an ambulance report, the pilot was awake and alert after the accident.

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Gretz, Robert
<b>Additional Participating Persons:</b>	Joseph Brown; FAA/FSDO; Allentown, PA Nicole Charnon; Continental Motors; Mobile, AL
<b>Original Publish Date:</b>	April 23, 2018
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=94358">https://data.ntsb.gov/Docket?ProjectID=94358</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).