



# **Aviation Investigation Final Report**

Location: FOLEY, Minnesota Accident Number: CHI94LA144

Date & Time: May 1, 1994, 20:20 Local Registration: N4104D

Aircraft: Helio H-800 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

THE PILOT-IN-COMMAND HAD FLOWN APPROXIMATELY 2.3 HOURS AFTER HIS INITIAL DEPARTURE WITH 45 GALLONS OF FUEL IN THE AMPHIBIOUS FLOAT EQUIPPED AIRPLANE. HIS ESTIMATION OF FUEL CONSUMPTION WAS 39 GALLONS PER HOUR (GPH) AT TAKEOFF POWER AND 23 GPH AT CRUISE. SEVERAL TOUCH AND GO LANDINGS WERE PERFORMED DURING THE FLIGHT. WHILE IN CRUISE FLIGHT A TOTAL LOSS OF ENGINE POWER OCCURRED AND A FORCED LANDING WAS MADE ON A GRAVEL ROAD. DURING LANDING, THE FLOAT NOSE WHEELS DUG INTO SOFT GRAVEL AND THE AIRPLANE FLIPPED OVER. POST CRASH INVESTIGATION REVEALED NO ENGINE ANOMOLIES, NO EVIDENCE OF FUEL IN THE TANKS, NOR ANY INDICATION OF FUEL SPILLAGE ON THE GROUND. THE PILOT STATED HE BELIEVED HE EXHAUSTED HIS FUEL SUPPLY.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT-IN-COMMAND'S FAILURE TO PERFORM ACCURATE FUEL CONSUMPTION CALCULATIONS. A FACTOR WAS THE SOFT GRAVEL ROAD LANDING AREA.

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE

**Findings** 

1. FLUID, FUEL - EXHAUSTION

2. (C) FUEL CONSUMPTION CALCULATIONS - INACCURATE - PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: NOSE OVER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION - LOOSE GRAVEL/SANDY

Page 2 of 6 CHI94LA144

#### **Factual Information**

On May 1, 1994, at 2020 hours central daylight time, an amphibian Helio H-800, N4104D, operated by T. J. Farms of St. Cloud, Minnesota, was substantially damaged 10 miles northeast of St. Cloud Municipal Airport, St. Cloud, Minnesota. The pilot experienced a total loss of engine power and made a forced landing on a gravel road. The amphibious float equipped airplane went over an embankment, dragged a float tip in soft gravel, and came to a stop upside down. The private pilot was uninjured. Visual meteorological conditions existed at the time of the accident and winds were calm. The flight originated at Princeton Municipal Airport, Princeton, Minnesota, at 2015 hours central standard time to reposition the airplane to a private strip at Long Lake, southeast of St. Cloud, Minnesota. No flight plan was filed.

Installation of amphibious floats had just been completed on the airplane. The pilot stated he had departed Cambridge Municipal Airport, Cambridge, Minnesota, 2.3 tachometer hours earlier with an estimated 45 gallons of fuel, performed touch and go landings, and was on his final leg of this flight. The pilot also stated he believes he exhausted his fuel supply. The fuel consumption of the Lycoming IO-720A engine installed on the H-800 is 33 gallons per hour (gph) at takeoff rated power and 23 gph at 75% cruise power as per Lycoming data. This was confirmed by the pilot and FAA inspector on scene. Post crash investigation revealed no fuel in the tanks, nor any indication of fuel spillage on the ground below the wreckage.

#### **Pilot Information**

1 Hot IIII of III ation			
Certificate:	Private	Age:	39,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	April 6, 1993
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	446 hours (Total, all aircraft), 74 hours (Total, this make and model), 25 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CHI94LA144

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Helio	Registration:	N4104D
Model/Series:	H-800 H-800	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	H-17
Landing Gear Type:	Amphibian	Seats:	4
Date/Type of Last Inspection:	October 29, 1993 Annual	Certified Max Gross Wt.:	4000 lbs
Time Since Last Inspection:	30 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	886 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-720 A/B
Registered Owner:	T. J. FARMS, LTD.	Rated Power:	400 Horsepower
Operator:	THOMAS J. HAMMER	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

	<u> </u>		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	STC ,1024 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	20:51 Local	Direction from Accident Site:	250°
<b>Lowest Cloud Condition:</b>	Scattered / 8000 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	5°C / -2°C
Precipitation and Obscuration:	No Obscuration; No Precipi	ation	
Departure Point:	PRINCETON , MN (PNM )	Type of Flight Plan Filed:	None
Destination:	LONG LAKE , MN	Type of Clearance:	None
Departure Time:	20:15 Local	Type of Airspace:	Class G

Page 4 of 6 CHI94LA144

## **Airport Information**

Airport:		Runway Surface Type:	
Airport Elevation:		<b>Runway Surface Condition:</b>	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced landing

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	45.660701,-93.899124(est)

Page 5 of 6 CHI94LA144

#### **Administrative Information**

Investigator In Charge (IIC):	Thomas, Matthew	
Additional Participating Persons:	O. T FRAMPTON; MINNEAPOLIS , MN	
Original Publish Date:	December 7, 1994	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=9515	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI94LA144