



# Aviation Investigation Final Report

---

|                                |                                      |                         |             |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| <b>Location:</b>               | Tunkhannock, Pennsylvania            | <b>Accident Number:</b> | GAA17CA293  |
| <b>Date &amp; Time:</b>        | May 18, 2017, 10:00 Local            | <b>Registration:</b>    | N34JM       |
| <b>Aircraft:</b>               | Piper PA 34                          | <b>Aircraft Damage:</b> | Substantial |
| <b>Defining Event:</b>         | Aerodynamic stall/spin               | <b>Injuries:</b>        | 1 None      |
| <b>Flight Conducted Under:</b> | Part 91: General aviation - Personal |                         |             |

---

## Analysis

The pilot reported that, during landing and while in ground affect, "the airplane suddenly, and without an aural stall warning, lost lift and was forced onto the runway." Subsequently, the nose gear landing collapsed, and the airplane veered off the runway to the right.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

The automated weather observation system located about 15 miles from the accident site reported that, about 6 minutes before the accident, the wind was from 230° at 10 knots. The pilot landed on runway 19.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain adequate airspeed and his exceedance of the airplane's critical angle of attack during landing in crosswind conditions, which resulted in an aerodynamic stall.

## Findings

---

|                             |   |
|-----------------------------|---|
| <b>Personnel issues</b>     | Aircraft control - Pilot                  |
| <b>Aircraft</b>             | Angle of attack - Not attained/maintained |
| <b>Aircraft</b>             | Airspeed - Not attained/maintained        |
| <b>Environmental issues</b> | Crosswind - Effect on operation           |

## Factual Information

### History of Flight

|                |   |
|----------------|---|
| <b>Landing</b> | Aerodynamic stall/spin (Defining event) |
| <b>Landing</b> | Hard landing                            |
| <b>Landing</b> | Landing gear collapse                   |
| <b>Landing</b> | Runway excursion                        |

### Pilot Information

|                                  |   |  |               |
|----------------------------------|---|--|---------------|
| <b>Certificate:</b>              | Commercial  | <b>Age:</b>                              | 49, Male      |
| <b>Airplane Rating(s):</b>       | Single-engine land; Single-engine sea; Multi-engine land  | <b>Seat Occupied:</b>                    | Left          |
| <b>Other Aircraft Rating(s):</b> | None  | <b>Restraint Used:</b>                   | Lap only      |
| <b>Instrument Rating(s):</b>     | Airplane  | <b>Second Pilot Present:</b>             | No            |
| <b>Instructor Rating(s):</b>     | None  | <b>Toxicology Performed:</b>             | No            |
| <b>Medical Certification:</b>    | Class 2 Without waivers/limitations   | <b>Last FAA Medical Exam:</b>            | May 19, 2017  |
| <b>Occupational Pilot:</b>       | No  | <b>Last Flight Review or Equivalent:</b> | June 15, 2016 |
| <b>Flight Time:</b>              | (Estimated) 3186 hours (Total, all aircraft), 1342 hours (Total, this make and model), 3126 hours (Pilot In Command, all aircraft), 24 hours (Last 90 days, all aircraft), 24 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft) |  |               |

## Aircraft and Owner/Operator Information

|                                      |                               |                                       |                 |
|--------------------------------------|-------------------------------|---------------------------------------|-----------------|
| <b>Aircraft Make:</b>                | Piper                         | <b>Registration:</b>                  | N34JM           |
| <b>Model/Series:</b>                 | PA 34 220T                    | <b>Aircraft Category:</b>             | Airplane        |
| <b>Year of Manufacture:</b>          | 2000                          | <b>Amateur Built:</b>                 |                 |
| <b>Airworthiness Certificate:</b>    | Normal                        | <b>Serial Number:</b>                 | 3449177         |
| <b>Landing Gear Type:</b>            | Retractable - Tricycle        | <b>Seats:</b>                         | 6               |
| <b>Date/Type of Last Inspection:</b> | May 19, 2016 Annual           | <b>Certified Max Gross Wt.:</b>       | 4700 lbs        |
| <b>Time Since Last Inspection:</b>   |                               | <b>Engines:</b>                       | 2 Reciprocating |
| <b>Airframe Total Time:</b>          | 1422 Hrs at time of accident  | <b>Engine Manufacturer:</b>           | Continental     |
| <b>ELT:</b>                          | C126 installed, not activated | <b>Engine Model/Series:</b>           | TSIO-360RB1B    |
| <b>Registered Owner:</b>             | AUTO MILESTONES LLC           | <b>Rated Power:</b>                   | 220 Horsepower  |
| <b>Operator:</b>                     | AUTO MILESTONES LLC           | <b>Operating Certificate(s) Held:</b> | None            |

## Meteorological Information and Flight Plan

|   |                                  |   |                   |
|---|----------------------------------|---|-------------------|
| <b>Conditions at Accident Site:</b>     | Visual (VMC)                     | <b>Condition of Light:</b>                  | Day               |
| <b>Observation Facility, Elevation:</b> | KAVP,962 ft msl                  | <b>Distance from Accident Site:</b>         | 15 Nautical Miles |
| <b>Observation Time:</b>                | 13:54 Local                      | <b>Direction from Accident Site:</b>        | 140°              |
| <b>Lowest Cloud Condition:</b>          | Clear                            | <b>Visibility</b>                           | 10 miles          |
| <b>Lowest Ceiling:</b>                  | None                             | <b>Visibility (RVR):</b>                    |                   |
| <b>Wind Speed/Gusts:</b>                | 10 knots /                       | <b>Turbulence Type Forecast/Actual:</b>     | / None            |
| <b>Wind Direction:</b>                  | 230°                             | <b>Turbulence Severity Forecast/Actual:</b> | / N/A             |
| <b>Altimeter Setting:</b>               | 29.96 inches Hg                  | <b>Temperature/Dew Point:</b>               | 28°C / 14°C       |
| <b>Precipitation and Obscuration:</b>   | No Obscuration; No Precipitation |   |                   |
| <b>Departure Point:</b>                 | FALMOUTH, MA (5B6)               | <b>Type of Flight Plan Filed:</b>           | None              |
| <b>Destination:</b>                     | Tunkhannock, PA (76N)            | <b>Type of Clearance:</b>                   | None              |
| <b>Departure Time:</b>                  | 08:20 Local                      | <b>Type of Airspace:</b>                    | Class G           |

## Airport Information

|                             |                 |                                  |  |
|-----------------------------|-----------------|----------------------------------|--|
| <b>Airport:</b>             | SKYHAVEN 76N    | <b>Runway Surface Type:</b>      | Asphalt  |
| <b>Airport Elevation:</b>   | 639 ft msl      | <b>Runway Surface Condition:</b> | Dry  |
| <b>Runway Used:</b>         | 19              | <b>IFR Approach:</b>             | None   |
| <b>Runway Length/Width:</b> | 2007 ft / 50 ft | <b>VFR Approach/Landing:</b>     | Full stop;Traffic pattern;Valley/terrain following |

## Wreckage and Impact Information

|                            |        |                             |                         |
|----------------------------|--------|-----------------------------|-------------------------|
| <b>Crew Injuries:</b>      | 1 None | <b>Aircraft Damage:</b>     | Substantial             |
| <b>Passenger Injuries:</b> |        | <b>Aircraft Fire:</b>       | None                    |
| <b>Ground Injuries:</b>    | N/A    | <b>Aircraft Explosion:</b>  | None                    |
| <b>Total Injuries:</b>     | 1 None | <b>Latitude, Longitude:</b> | 41.5275,-75.945831(est) |

## Preventing Similar Accidents

Prevent Aerodynamic Stalls at Low Altitude (SA-019)

### The Problem

While maneuvering an airplane at low altitude in visual meteorological conditions, many pilots fail to avoid conditions that lead to an aerodynamic stall, recognize the warning signs of a stall onset, and apply appropriate recovery techniques. Many stall accidents result when a pilot is momentarily distracted from the primary task of flying, such as while maneuvering in the airport traffic pattern, during an emergency, or when fixating on ground objects.

### What can you do?

- Be honest with yourself about your knowledge of stalls and your preparedness to recognize and handle a stall situation in your airplane. Seek training to ensure that you fully understand the stall phenomenon, including angle-of attack (AOA) concepts and how elements such as weight, center of gravity, turbulence, maneuvering loads, and other factors affect an airplane's stall characteristics.
- Remember that an aerodynamic stall can occur at any airspeed, at any attitude, and with any engine power setting.
- Remember that the stall airspeeds marked on the airspeed indicator (for example, the bottom of the green arc and the bottom of the white arc) typically represent steady flight speeds at 1G at the airplane's maximum gross weight in the specified configuration. Maneuvering loads and other factors can increase the airspeed at which the airplane will stall. For example, increasing bank angle can increase stall speed exponentially. Check your airplane's handbook for information.
- Reducing AOA by lowering the airplane's nose at the first indication of a stall is the most important immediate response for stall avoidance and stall recovery.
- Manage distractions when maneuvering at low altitude so that they do not interfere with the primary task of flying.
- Resist the temptation to perform maneuvers in an effort to impress people, including passengers, other pilots, persons on the ground, or others via an onboard camera. "Showing off" can be a deadly distraction because it diverts your attention away from the primary task of safe flying.
- Understand that the stall characteristics of an unfamiliar airplane may differ substantially from those of airplanes with which you have more flight experience.

See <https://www.nts.gov/Advocacy/safety-alerts/Documents/SA-019.pdf> for additional resources.

The NTSB presents this information to prevent recurrence of similar accidents. Note that this should not be considered guidance from the regulator, nor does this supersede existing FAA Regulations (FARs).

## Administrative Information

|  |   |
|--|---|
| <b>Investigator In Charge (IIC):</b>     | Vanover, Jackie   |
| <b>Additional Participating Persons:</b> | Joseph Sablan; FAA; Allentown, PA   |
| <b>Original Publish Date:</b>            | January 23, 2018  |
| <b>Last Revision Date:</b>               |   |
| <b>Investigation Class:</b>              | <a href="#">Class</a>   |
| <b>Note:</b>                             | This accident report documents the factual circumstances of this accident as described to the NTSB.   |
| <b>Investigation Docket:</b>             | <a href="https://data.nts.gov/Docket?ProjectID=95205">https://data.nts.gov/Docket?ProjectID=95205</a> |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).