



# Aviation Investigation Final Report

---

<b>Location:</b>	Portland, Indiana	<b>Accident Number:</b>	CEN17LA205
<b>Date &amp; Time:</b>	May 26, 2017, 17:20 Local	<b>Registration:</b>	N604KA
<b>Aircraft:</b>	AMSTUTZ CURTIS J BD-5B	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (total)	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Flight test		

---

## Analysis

The private pilot, who was the builder of the airplane, stated that the purpose of the test flight was to obtain rate of climb data on the airplane, which had recently been completed. Following the sixth climb of the flight, the engine began to run rough. The pilot turned back toward the airport and entered the traffic pattern, and the engine experienced a total loss of power. The pilot determined that the airplane would not reach the runway and performed an off-airport landing in a field. The field was soft and contained high vegetation, which resulted in a ground loop during landing.

The pilot noted that, during the flight, the No. 1 cylinder exhaust gas temperature and cylinder head temperature had dropped, indicating that the No. 1 cylinder was not firing properly. It was after the No. 1 cylinder quit firing that the No. 2 cylinder also quit firing. A postaccident examination of the engine revealed that the wire in the No. 1 cylinder connector between the engine control unit and the fuel injector was not properly crimped at the connector, which allowed the wire to be pulled back. In addition, a wire to the No. 2 connector was found broken where the wire had been spliced. This wire most likely separated at the spliced area due to engine vibrations after the No. 1 cylinder ceased operating.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A failure of the wiring between the engine control unit and the fuel injector, which resulted in a total loss of engine power.

## Findings

<b>Aircraft</b>	Electrical pwr sys wiring - Failure
<b>Environmental issues</b>	Wet/muddy terrain - Contributed to outcome

## Factual Information

### History of Flight

<b>Maneuvering</b>	Loss of engine power (partial)
<b>Approach-VFR pattern base</b>	Loss of engine power (total) (Defining event)
<b>Landing</b>	Off-field or emergency landing
<b>Landing-landing roll</b>	Landing gear collapse

On May 26, 2017, at 1720 eastern daylight time, an Amstutz BD-5B amateur built airplane, N604KA, was involved in an off airport forced landing, following a loss of engine power in Portland, Indiana. The pilot was not injured. The airplane was substantially damaged. The airplane was registered to and operated by an individual under the provisions of 14 *Code of Federal Regulations* Part 91 as an engineering test flight. Visual meteorological conditions prevailed for the flight, which was not operated on a flight plan. The local flight originated from the Portland Municipal Airport (PLD), Portland, Indiana, at 1650.

The pilot reported the airplane had 5.8 flight hours since he completed building it and the purpose of the flight was to obtain rate of climb data. Following the 6th climb, while at an altitude of 3,500 ft above mean seal level, the engine began to run rough. The pilot entered a left downwind at PLD and descended for a landing approach. The pilot reported he switched fuel tanks and performed a magneto check, neither of which corrected the engine roughness. The pilot noticed the cylinder head temperature and the exhaust gas temperature for the No. 1 cylinder decreased, indicating the No. 1 cylinder was not firing. As he turned onto base leg, the engine lost all power. The pilot realized he was not going to be able to make it to the runway, so he selected a field in which to land. The field contained 3 ft tall vegetation and was soft from recent rain. About 170 ft into the landing roll, the landing gear collapsed, and the airplane ground looped which resulted in damage to the flaps, ailerons, and horizontal stabilator.

The airplane was equipped with a 2-cycle, 2-cylinder Hirth 3203E engine. A postaccident inspection of the engine by the pilot revealed there were separated wires in the connectors between the engine control unit (ECU) and the fuel injectors for both the No. 1 and No. 2 cylinders. The wires for the No. 1 cylinder connector appeared to be crimped properly with the insulation reaching the crimped connector. The pilot tugged on the wire and about 1/2 inch of the copper wire came out of the insulation. The pilot removed the connector for the No. 2 cylinder and found a broken wire at the splice connector that he had installed the month prior to the accident.

The pilot stated that the engine was about 15 years old, even though the engine had 15 hours of total operating time. It is unknown when the No. 1 cylinder connector was installed on the engine.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	48, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Center
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	March 21, 2016
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	212 hours (Total, all aircraft), 6 hours (Total, this make and model), 183 hours (Pilot In Command, all aircraft), 2 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	AMSTUTZ CURTIS J	<b>Registration:</b>	N604KA
<b>Model/Series:</b>	BD-5B	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2016	<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	1
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	1
<b>Date/Type of Last Inspection:</b>	September 26, 2016 Condition	<b>Certified Max Gross Wt.:</b>	800 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	5.8 Hrs	<b>Engine Manufacturer:</b>	Hirth
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	3203E
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	65 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	PLD,925 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	16:30 Local	<b>Direction from Accident Site:</b>	240°
<b>Lowest Cloud Condition:</b>	Scattered / 7000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	6 knots /	<b>Turbulence Type Forecast/Actual:</b>	/ None
<b>Wind Direction:</b>	200°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.84 inches Hg	<b>Temperature/Dew Point:</b>	24°C / 15°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Portland, IN (PLD )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Portland, IN (PLD )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	16:50 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	Portland Municipal PLD	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	925 ft msl	<b>Runway Surface Condition:</b>	Wet
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	40.451946,-84.979721(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Sullivan, Pamela
<b>Additional Participating Persons:</b>	Louis Soto; FAA; Indianapolis, IN
<b>Original Publish Date:</b>	November 15, 2018
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=95270">https://data.nts.gov/Docket?ProjectID=95270</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).