

Aviation Investigation Final Report

Location: Albuquerque, New Mexico Accident Number: GAA18CA016

Date & Time: October 6, 2017, 08:00 Local Registration: N123UT

Aircraft: ULTRAMAGIC SA T210 Aircraft Damage: Substantial

Defining Event: Ground collision Injuries: 1 Serious, 1 Minor, 10

None

Flight Conducted Under: Part 91: General aviation - Aerial observation

Analysis

The Ultramagic balloon pilot reported that, during a balloon festival, after a local sightseeing flight, he landed the balloon and decided to wait for the ground crew to locate the balloon before deflating. He added that, as the balloon was deflating, he "heard a basket sliding across the top of [his] balloon." The balloon rotated counter-clockwise, and the balloon basket, still loaded with passengers, rolled upside down.

The Ultramagic balloon sustained substantial damage to the burner rack. One passenger sustained serious injuries.

The Lindstrand balloon pilot reported that, during landing, there were two balloons in his flightpath. He added that he climbed and passed the first balloon but was unable to pass the second balloon, and "I brushed him with my basket on the top of his balloon." He landed the balloon without further incident.

The Ultramagic pilot and the Lindstrand operations manager reported that there were no preaccident mechanical failures or malfunctions with the balloons that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The other pilot's failure to maintain adequate clearance from a balloon on the ground during landing.

Findings

Environmental issues	Aircraft - Effect on operation
Personnel issues	Monitoring other aircraft - Pilot of other aircraft

Page 2 of 11 GAA18CA016

Factual Information

History of Flight

Standing Ground collision (Defining event)	Standing	Ground collision (Defining event)
--	----------	-----------------------------------

Pilot Information

Certificate:	Commercial	Age:	62,Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Balloon	Restraint Used:	None
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	September 12, 2017
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 21, 2016
Flight Time:	(Estimated) 11028 hours (Total, all aircraft), 2148 hours (Total, this make and model), 10992 hours (Pilot In Command, all aircraft), 105 hours (Last 90 days, all aircraft), 42 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Page 3 of 11 GAA18CA016

Aircraft and Owner/Operator Information

Aircraft Make:	ULTRAMAGIC SA	Registration:	N123UT
Model/Series:	T210 NO SERIES	Aircraft Category:	Balloon
Year of Manufacture:	2007	Amateur Built:	
Airworthiness Certificate:	Balloon	Serial Number:	210/42
Landing Gear Type:	N/A	Seats:	12
Date/Type of Last Inspection:	May 24, 2017 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 None
Airframe Total Time:	815.4 Hrs as of last inspection	Engine Manufacturer:	
ELT:		Engine Model/Series:	
Registered Owner:	PACIFIC RIM ADVENTURES INC DBA	Rated Power:	
Operator:	PACIFIC RIM ADVENTURES INC DBA	Operating Certificate(s) Held:	None
Operator Does Business As:	Sky's The Limit Balloon Adventure	Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KABQ,5314 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	12:52 Local	Direction from Accident Site:	186°
Lowest Cloud Condition:	Few / 1300 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 8000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.09 inches Hg	Temperature/Dew Point:	17°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Albuquerque, NM	Type of Flight Plan Filed:	VFR
Destination:	Albuquerque, NM	Type of Clearance:	VFR
Departure Time:	07:10 Local	Type of Airspace:	Class G

Page 4 of 11 GAA18CA016

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Serious, 10 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 Minor, 10 None	Latitude, Longitude:	35.198055,-106.596389(est)

Page 5 of 11 GAA18CA016

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Vernon R Rockett; FAA; Albuquerque, NM
Original Publish Date:	January 11, 2018
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=96215

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 11 GAA18CA016





Aviation Investigation Final Report

Location: Albuquerque, New Mexico Accident Number: GAA18CA016

Date & Time: October 6, 2017, 08:00 Local **Registration:** C-FCKX

Aircraft: Lindstrand LBL240A Aircraft Damage: None

Defining Event: Ground collision **Injuries:** 13 None

Flight Conducted Under: Part 91: General aviation - Aerial observation

Analysis

The Ultramagic balloon pilot reported that, during a balloon festival, after a local sightseeing flight, he landed the balloon and decided to wait for the ground crew to locate the balloon before deflating. He added that, as the balloon was deflating, he "heard a basket sliding across the top of [his] balloon." The balloon rotated counter-clockwise, and the balloon basket, still loaded with passengers, rolled upside down.

The Ultramagic balloon sustained substantial damage to the burner rack. One passenger sustained serious injuries.

The Lindstrand balloon pilot reported that, during landing, there were two balloons in his flightpath. He added that he climbed and passed the first balloon but was unable to pass the second balloon, and "I brushed him with my basket on the top of his balloon." He landed the balloon without further incident.

The Ultramagic pilot and the Lindstrand operations manager reported that there were no preaccident mechanical failures or malfunctions with the balloons that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain adequate clearance from a balloon on the ground during landing.

Findings

Personnel issues	Monitoring other aircraft - Pilot
Environmental issues	Aircraft - Effect on operation
Aircraft	Altitude - Not attained/maintained

Page 8 of 11 GAA18CA016

Factual Information

History of Flight

Landing	Collision during takeoff/land

Pilot Information

Certificate:	Foreign; Private	Age:	28.Male
Certificate.	i oreign, r nvate	Age.	20, IVI ale
Airplane Rating(s):	None	Seat Occupied:	None
Other Aircraft Rating(s):	Balloon	Restraint Used:	None
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	March 2, 2014
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	May 11, 2017
Flight Time:	(Estimated) 743 hours (Total, all aircraft), 40 hours (Total, this make and model), 734 hours (Pilot In Command, all aircraft), 40 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Lindstrand	Registration:	C-FCKX
Model/Series:	LBL240A	Aircraft Category:	Balloon
Year of Manufacture:	1995	Amateur Built:	
Airworthiness Certificate:	Balloon; Normal	Serial Number:	165
Landing Gear Type:	N/A	Seats:	13
Date/Type of Last Inspection:	February 23, 2017 100 hour	Certified Max Gross Wt.:	4270 lbs
Time Since Last Inspection:		Engines:	1 None
Airframe Total Time:	1135.2 Hrs at time of accident	Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	Sundance Balloons (2008) Ltd	Rated Power:	
Operator:	Sundance Balloons (2008) Ltd	Operating Certificate(s) Held:	None
Operator Does Business As:	Sundance Balloons	Operator Designator Code:	

Page 9 of 11 GAA18CA016

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KABQ,5314 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	12:52 Local	Direction from Accident Site:	186°
Lowest Cloud Condition:	Few / 1300 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 8000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.09 inches Hg	Temperature/Dew Point:	17°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Albuquerque, NM	Type of Flight Plan Filed:	None
Destination:	Albuquerque, NM	Type of Clearance:	None
Departure Time:	07:38 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	None
Passenger Injuries:	12 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	13 None	Latitude, Longitude:	35.198055,-106.596389(est)

Page 10 of 11 GAA18CA016

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn	
Additional Participating Persons:	Vernon R Rockett; FAA; Albuquerque, NM	
Original Publish Date:	January 11, 2018	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.	
Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=96215		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 11 of 11 GAA18CA016