



# Aviation Investigation Final Report

<b>Location:</b>	Albany, Texas	<b>Accident Number:</b>	CEN18LA069
<b>Date &amp; Time:</b>	January 8, 2018, 13:45 Local	<b>Registration:</b>	N797JR
<b>Aircraft:</b>	ROBINSON HELICOPTER COMPANY R44 II	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Unknown or undetermined	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The commercial pilot stated that he was using the helicopter to round up cattle. He applied power to stabilize in a hover about 50 ft above the ground when he heard a single loud bang and "felt it in the pedals." The helicopter spun to the right, and the pilot applied full left pedal, which had no effect on the helicopter. The pilot stated that after about two spins, he entered an autorotation to remove torque from the rotor system. The helicopter contacted trees as it descended to the ground and came to rest upright with the tailboom separated.

Postaccident examination of the wreckage did not reveal any evidence of mechanical malfunctions or failures of the main rotor and tail rotor systems that would have precluded normal operation; thus, the reason for the loss of control could not be determined.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A loss of helicopter control for reasons that could not be determined because postaccident examination did not reveal any evidence of mechanical malfunctions or failures of the main rotor and tail rotor systems that would have precluded normal operation.

## Findings

---

**Not determined**

(general) - Unknown/Not determined

## Factual Information

### History of Flight

<b>Maneuvering-hover</b>	Unknown or undetermined (Defining event)
<b>Autorotation</b>	Hard landing

\*\*\*This report was modified on 5/15/2019. Please see the docket for this accident to view the original report.\*\*\*

On January 8, 2018, at 1345 central standard time, a Robinson R44 helicopter, N797JR, collided with trees and the terrain during an autorotation near Albany, Texas. The commercial pilot was not injured. The helicopter was substantially damaged. The helicopter was registered to S2 Helicopter Services and was operated by an individual as a Title 14 *Code of Federal Regulations* Part 91 personal flight. Day visual meteorological conditions prevailed. The flight was not operated on a flight plan. The local flight originated from a ranch in Albany, Texas, at 1310.

The pilot stated he was using the helicopter to roundup cattle when the accident occurred. He reported he applied power to stabilize in a hover about 50 ft above the ground, when he heard a single loud bang and "felt it in the pedals." The helicopter spun to the right and the pilot applied full left pedal which had no effect. The pilot stated that after about 2 spins, he entered an autorotation to remove torque from the rotor system. The helicopter contacted trees as it descended to the ground. The helicopter came to rest upright with the tail boom separated.

The pilot reported that he was not sure if there was a "mechanical problem" or not. His recommendation was "Conduct a better clearing turn to ensure that nothing was around including animals/birds" and to "maintain more forward airspeed in case of emergency."

The helicopter was sitting upright on the skids. The fuselage was intact and the tailboom was separated just forward of the empennage. Minor crushing damage was visible on the right side of the helicopter aft of the cabin area. Crush damage was visible on the left side of the helicopter above the front and rear skid struts. The main rotor blades, main rotor blade hub, and main rotor mast were intact. One of the main rotor blades exhibited minor bending near the outboard section of the blade. The other blade had a hole in the blade near the tip and the leading edge of the blade at the tip was pulled away from the remainder of the blade.

The empennage and tailrotor were separated from the tailboom. The tailrotor drive shaft separated at the aft flex plate. The drive shaft remained connected to the clutch assembly. The main rotor blades turned when the tailrotor drive shaft was rotated by hand. Ratchet marks were visible inside the tailboom near the aft flex plate. Corresponding damage was visible on the flex plate and drive shaft.

The trailing edge of the lower vertical stabilizer contained impact damage to the rear edge of the surface, pushing the skin forward toward the leading edge. The tail rotor blade assembly remained attached to

the tail rotor gearbox. One tail rotor blade was bent outward 90 ° at the blade root. The other blade was bent out about 20° the blade root. The blade was free to turn when rotated by hand.

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	28, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Helicopter	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Instrument helicopter	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	July 18, 2017
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	March 11, 2016
<b>Flight Time:</b>	3000 hours (Total, all aircraft), 1700 hours (Total, this make and model), 2450 hours (Pilot In Command, all aircraft), 120 hours (Last 90 days, all aircraft), 29 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	ROBINSON HELICOPTER COMPANY	<b>Registration:</b>	N797JR
<b>Model/Series:</b>	R44 II II	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>	2006	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	11030
<b>Landing Gear Type:</b>	N/A; Skid	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	June 3, 2017 Annual	<b>Certified Max Gross Wt.:</b>	2120 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2058 Hrs	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	IO-540
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	0 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	BKD,1284 ft msl	<b>Distance from Accident Site:</b>	25 Nautical Miles
<b>Observation Time:</b>	19:55 Local	<b>Direction from Accident Site:</b>	90°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	7 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	5 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	360°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.17 inches Hg	<b>Temperature/Dew Point:</b>	16°C / -1°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Albany, TX	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Albany, TX	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	13:10 Local	<b>Type of Airspace:</b>	Class G

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	32.729999,-99.309448(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Sullivan, Pamela
<b>Additional Participating Persons:</b>	Anthony Leinneweber; FAA; Lubbock, TX
<b>Original Publish Date:</b>	July 8, 2019
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=96581">https://data.ntsb.gov/Docket?ProjectID=96581</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).