



Aviation Investigation Final Report

| | | | |
|--------------------------------|--|-------------------------|-------------|
| Location: | Bunn, North Carolina | Accident Number: | ERA18LA087 |
| Date & Time: | February 24, 2018, 12:30 Local | Registration: | N8401V |
| Aircraft: | Aero Commander CALLAIR A 9 | Aircraft Damage: | Substantial |
| Defining Event: | Altitude deviation | Injuries: | 1 Minor |
| Flight Conducted Under: | Part 91: General aviation - Glider tow | | |

Analysis

The flight instructor and student on board the glider were conducting an aerotow takeoff with the student manipulating the controls. About 300 ft above ground level (agl), the glider encountered a gust, causing it to move out of position behind the tow plane, and the tow rope developed slack. The student corrected, and as the tow rope tightened, the glider continued up and to the left "at an alarming rate" and became "extremely out of position." The instructor assumed control of the glider and attempted to release from the tow plane, noting that more force than usual was required, and the glider release activated during the third attempt. The glider returned to the runway and landed uneventfully.

The pilot of the towplane stated that the tow was "very turbulent" and he noted that the glider was out of position. He stated that the airplane's nose was "suddenly jerked about 35° left" and the tail of the airplane began to rise. He attempted to release the glider, but had difficulty reaching the release handle, and the glider released "a split second before" he was able to do so, at an estimated altitude about 75 ft agl. The airplane's left wing contacted trees and the airplane impacted the ground nearly inverted.

Examination of the glider tow release hook revealed that, although the force required to activate the release was higher than that specified in the maintenance manual, this condition did not contribute to the accident, and the flight instructor's difficulty actuating the release mechanism was most likely the result of side-loading of the release mechanism due to the glider being out of position.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The glider instructor's delayed remedial action when the glider became out of position during aerotow, which resulted in excessive side-loading of the release hook and a delay in the glider's release from tow, which resulted in the towplane's descent and impact with trees.

Findings

| | |
|-------------------------|--|
| Personnel issues | Delayed action - Instructor/check pilot |
| Aircraft | Heading/course - Not attained/maintained |
| Aircraft | (general) - Capability exceeded |
| Personnel issues | Strength - Pilot of other aircraft |

Factual Information

History of Flight

| | |
|-----------------------------|-------------------------------------|
| Takeoff | Glider tow event |
| Initial climb | Altitude deviation (Defining event) |
| Maneuvering | Collision with terr/obj (non-CFIT) |
| Uncontrolled descent | Collision with terr/obj (non-CFIT) |

On February 24, 2018, about 1230 eastern standard time, an Aero Commander Callair A-9 (Callair A-9), N8401V, was substantially damaged when it was involved in an accident near Bunn, North Carolina. The commercial pilot sustained a minor injury. The airplane was operated as a Title 14 Code of Federal Regulations Part 91 glider tow flight.

The flight instructor of the Schweizer SGS-2-33A glider (N1186S) being towed aloft reported that 2 previous flights earlier that day, the student was demonstrating good progress in controlling the glider off tow and showing beginning competency on tow but occasionally required his corrections, which improved on the 2nd flight. The student executed the 3rd takeoff under control and when above the treeline with moderate turbulence which was similar to the conditions during the first 2 flights, a gust occurred. The glider moved down and to the right relative to the tow airplane with resulting slight amount of slack in the tow line. The student made appropriate control inputs to move the glider up and to the left, but the glider continued up and to the left at, "an alarming rate, reminding me of a winch launch, and we zoomed up to a maximum of what [he estimated] as [about] 400 ft [above ground level]", placing the glider in "...extremely out of position." About that time he took over the controls and made large forward and right stick movements, in addition to deploying full spoilers. Because the situation was not improving he determined they needed to release immediately and pulled twice with more force than usually required, then when the glider did not release which he later attributed to the side loads, he looked to confirm he was pulling the correct control and on the 3rd attempt yanked as hard as he could and the tow line released. He maneuvered the glider for an uneventful downwind landing.

The pilot of the Callair A-9 reported that the moment the glider became airborne, "it was a very turbulent tow" with the glider moving erratically back and forth. The flight continued and when he looked into the mirror, the glider was out of position, and he noted slack in the towline. The tow line slack went out causing the nose of the airplane to jerk about 35° to the left, which reduced the airspeed considerably. The glider continued to climb, causing the tow plane to be in a nose-low attitude. About that time, he attempted to release the glider, but because of the position of the tow release handle in the cockpit, he had difficulty reaching it. He eventually was able to reach the handle, but the glider released a split second before he could initiate the release. When the glider was released, the airplane was about 75 feet agl, or about 25 to 45 feet above the tree tops. The left wing then impacted trees, and the airplane then impacted the ground nearly fully inverted. The pilot reported no preimpact mechanical failure or malfunction.

Postaccident examination of the Callair A-9 by a Federal Aviation Administration inspector revealed the elevator control cable tensions were near zero and the rigging of the elevator was off related to the position relative to the horizontal stabilizer and the control stick in the cockpit. Examination of the Callair A-9 and Schweizer glider by a mechanic revealed the tow release of the Callair A-9 was within limits, while the tow release of the glider was above the maintenance manual limits; the amount was not specified.

Pilot Information

| | | | |
|----------------------------------|--|--|-------------------|
| Certificate: | Commercial; Flight instructor | Age: | 74, Male |
| Airplane Rating(s): | Single-engine land; Single-engine sea | Seat Occupied: | Center |
| Other Aircraft Rating(s): | Glider | Restraint Used: | 4-point |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | Airplane single-engine | Toxicology Performed: | No |
| Medical Certification: | Class 3 Without waivers/limitations | Last FAA Medical Exam: | November 21, 2016 |
| Occupational Pilot: | Yes | Last Flight Review or Equivalent: | July 9, 2016 |
| Flight Time: | 12252 hours (Total, all aircraft), 350 hours (Total, this make and model), 12100 hours (Pilot In Command, all aircraft), 33 hours (Last 90 days, all aircraft), 18 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|-----------------------------------|---------------------------------------|-----------------|
| Aircraft Make: | Aero Commander | Registration: | N8401V |
| Model/Series: | CALLAIR A 9 NO SERIES | Aircraft Category: | Airplane |
| Year of Manufacture: | 1970 | Amateur Built: | |
| Airworthiness Certificate: | Restricted (Special) | Serial Number: | 1601 |
| Landing Gear Type: | Tailwheel | Seats: | 1 |
| Date/Type of Last Inspection: | July 9, 2017 Annual | Certified Max Gross Wt.: | 3800 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 4445.06 Hrs as of last inspection | Engine Manufacturer: | Lycoming |
| ELT: | Not installed | Engine Model/Series: | O-540-A1D5 |
| Registered Owner: | On file | Rated Power: | 235 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| | | | |
|---|----------------------------------|---|---------------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | LHZ,368 ft msl | Distance from Accident Site: | 7 Nautical Miles |
| Observation Time: | 10:35 Local | Direction from Accident Site: | 326° |
| Lowest Cloud Condition: | | Visibility | 10 miles |
| Lowest Ceiling: | Broken / 1500 ft AGL | Visibility (RVR): | |
| Wind Speed/Gusts: | 3 knots / | Turbulence Type Forecast/Actual: | Terrain-Induced / Unknown |
| Wind Direction: | 220° | Turbulence Severity Forecast/Actual: | Moderate / Moderate |
| Altimeter Setting: | 30.23 inches Hg | Temperature/Dew Point: | 19°C / 16°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Bunn, NC (7NC5) | Type of Flight Plan Filed: | None |
| Destination: | Bunn, NC (7NC5) | Type of Clearance: | None |
| Departure Time: | 10:44 Local | Type of Airspace: | |

Wreckage and Impact Information

| | | | |
|----------------------------|---------|-----------------------------|---------------------------|
| Crew Injuries: | 1 Minor | Aircraft Damage: | Substantial |
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Minor | Latitude, Longitude: | 35.926666,-78.248054(est) |

Administrative Information

| | |
|--|---|
| Investigator In Charge (IIC): | Monville, Timothy |
| Additional Participating Persons: | Jerry L Toms; FAA/FSDO; Greensboro, NC |
| Original Publish Date: | December 3, 2020 |
| Last Revision Date: | |
| Investigation Class: | Class 3 |
| Note: | The NTSB did not travel to the scene of this accident. |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=96791 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).