



Aviation Investigation Final Report

Location: Pixley, California Accident Number: WPR18CA096

Date & Time: February 28, 2018, 15:30 Local Registration: N7800S

Aircraft: Bell 47G Aircraft Damage: Substantial

Defining Event: Fuel exhaustion **Injuries:** 1 Serious

Flight Conducted Under: Part 137: Agricultural

Analysis

The pilot reported that, after landing and during the loading for the next chemical agricultural application flight with the engine running, he exited the helicopter to speak to the owner of the property he was spraying. He could not remember if he had instructed the ground crewman to fuel the helicopter or not. Additionally, the pilot stated that, before takeoff, he failed to check the fuel level and was unaware that the ground crewman had not refueled the helicopter. After takeoff and completing only one spray pass, the engine lost power. The pilot opined that he "just ran out of fuel." Unable to make it back to the loading area, he landed in a grove of trees, which resulted in substantial damage to the fuselage. The pilot also mentioned that due to the approaching rain, he was in a hurry to get the field sprayed before it arrived.

The pilot reported that there were no preimpact mechanical anomalies with the helicopter or engine that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to fuel starvation, which resulted from the pilot's failure to ensure that adequate fuel was on board for the flight. Contributing to the accident was the pilot's self-induced pressure to complete the flight due to impending rain.

Findings

Aircraft Fuel - Fluid level

Personnel issues Fuel planning - Pilot

Personnel issues Forgotten action/omission - Pilot

Environmental issues Tree(s) - Effect on operation

Personnel issues Motivation/respond to pressure - Pilot

Page 2 of 6 WPR18CA096

Factual Information

History of Flight

Prior to flight	Aircraft servicing event	
Maneuvering-low-alt flying	Fuel exhaustion (Defining event)	
Emergency descent	Off-field or emergency landing	
Emergency descent	Collision with terr/obj (non-CFIT)	
Maneuvering-low-alt flying	Loss of engine power (total)	

Pilot Information

Certificate:	Commercial	Age:	53,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	September 7, 2017
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	July 6, 2016
Flight Time:	(Estimated) 17000 hours (Total, all a (Last 90 days, all aircraft)	aircraft), 17000 hours (Total, this make	e and model), 10 hours

Page 3 of 6 WPR18CA096

Aircraft and Owner/Operator Information

Bell	Registration:	N7800S
47G 5	Aircraft Category:	Helicopter
1966	Amateur Built:	
Restricted (Special)	Serial Number:	7854
Skid	Seats:	2
April 7, 2017 Annual	Certified Max Gross Wt.:	700 lbs
	Engines:	1 Reciprocating
10132 Hrs at time of accident	Engine Manufacturer:	Lycoming
Not installed	Engine Model/Series:	VO-435
On file	Rated Power:	260 Horsepower
On file	Operating Certificate(s) Held:	Agricultural aircraft (137)
	47G 5 1966 Restricted (Special) Skid April 7, 2017 Annual 10132 Hrs at time of accident Not installed On file	47G 5 Aircraft Category: 1966 Amateur Built: Restricted (Special) Serial Number: Skid Seats: April 7, 2017 Annual Certified Max Gross Wt.: Engines: 10132 Hrs at time of accident Not installed Engine Manufacturer: Not installed Engine Model/Series: On file Operating Certificate(s)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PTV,443 ft msl	Distance from Accident Site:	8 Nautical Miles
Observation Time:	15:56 Local	Direction from Accident Site:	50°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	110°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.19 inches Hg	Temperature/Dew Point:	15°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Pixley, CA	Type of Flight Plan Filed:	None
Destination:	Pixley, CA	Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class E

Page 4 of 6 WPR18CA096

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	35.936389,-119.192497

Page 5 of 6 WPR18CA096

Administrative Information

Investigator In Charge (IIC):	Little, Thomas
Additional Participating Persons:	Bjorn Beijens; Federal Aviation Administration; Fresno, CA
Original Publish Date:	June 14, 2018
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=96804

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR18CA096