



Aviation Investigation Final Report

Location:	Sioux Falls, South Dakota	Accident Number:	CEN18LA164
Date & Time:	April 29, 2018, 22:30 Local	Registration:	N172GA
Aircraft:	Beech 1900C	Aircraft Damage:	Substantial
Defining Event:	Sys/Comp malf/fail (non-power)	Injuries:	1 None
Flight Conducted Under:	Part 135: Air taxi & commuter - Non-scheduled		

Analysis

As the twin-engine, turbopropeller-equipped airplane started to taxi for takeoff, the right main landing gear collapsed, deforming the aft center wing lower spar cap. A postaccident examination of the airplane revealed that the right main landing gear drag brace bolt failed at the wing forward attach point. As the airplane moved forward, the strut pivoted aft, collapsing the landing gear. The drag brace bolt was not retained, and the reason for its failure could not be determined based on the available information.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Failure of the right main landing gear drag brace bolt for reasons that could not be determined based on the available information.

Findings	
Aircraft	Main landing gear attach sec - Failure
Aircraft	Spar (on wing) - Fatigue/wear/corrosion

Factual Information

History of Flight	
Taxi	Sys/Comp malf/fail (non-power) (Defining event)
Taxi	Landing gear collapse

On April 29, 2018, about 2230 central daylight time, a Beech 1900C, N172GA, was substantially damaged when the right main landing gear collapsed as the airplane started to taxi for takeoff at Joe Foss Field Airport (FSD), Sioux Falls, South Dakota. The airline transport pilot was not injured. The airplane was registered to and operated by Alpine Aviation, doing business as Alpine Air Express, under the provisions of Title 14 *Code of Federal Regulations* Part 135 as a non-scheduled domestic cargo flight. Visual meteorological conditions prevailed at the airport at the time of the accident, and an instrument flight rules flight plan had been filed. The flight was originating from FSD, and was destined for Rapid City Regional Airport (RAP), Rapid City, South Dakota.

According to Federal Aviation Administration (FAA) inspectors, the airplane had just moved forward to taxi for takeoff when the right main landing gear collapsed. A postaccident examination of the airplane revealed the right main landing gear drag brace bolt failed at the wing forward attach point. The drag brace bolt was not retained for further examination. The strut pivoted aft when the airplane moved forward, and the landing gear collapsed. The aft center wing lower spar cap was dented and deformed up to 0.090". Further examination found pitting corrosion on the spar cap.

Phot information			
Certificate:	Airline transport; Commercial; Flight instructor	Age:	57,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	October 13, 2017
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 28, 2017
Flight Time:	13968 hours (Total, all aircraft), 1000 hours (Total, this make and model), 8000 hours (Pilot In Command, all aircraft), 133 hours (Last 90 days, all aircraft), 50 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N172GA
Model/Series:	1900C	Aircraft Category:	Airplane
Year of Manufacture:	1982	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	UB-11
Landing Gear Type:	Retractable - Tricycle	Seats:	2
Date/Type of Last Inspection:	March 10, 2018 AAIP	Certified Max Gross Wt.:	16600 lbs
Time Since Last Inspection:	117 Hrs	Engines:	2 Turbo prop
Airframe Total Time:	41851 Hrs at time of accident	Engine Manufacturer:	Pratt & Whitney
ELT:	C91 installed, not activated	Engine Model/Series:	PT6A-65B
Registered Owner:	Alpine Aviation, Inc.	Rated Power:	1100 Horsepower
Operator:	Alpine Aviation, Inc.	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:	Alpine Air Express	Operator Designator Code:	TIMA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night
Observation Facility, Elevation:	KFSD,1429 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	22:56 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	160°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	20°C / 7°C
Precipitation and Obscuration:			
Departure Point:	Sioux Falls, SD (FSD)	Type of Flight Plan Filed:	IFR
Destination:	Rapid City, SD (RAP)	Type of Clearance:	None
Departure Time:	22:30 Local	Type of Airspace:	Class D

Airport Information

Airport:	Joe Foss Field FSD	Runway Surface Type:	
Airport Elevation:	1429 ft msl	Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	43.581943,-96.741943(est)

Administrative Information

Investigator In Charge (IIC):	Scott, Arnold
Additional Participating Persons:	Kenneth Joyce; FAA Flight Standards District Office; Salt Lake City, UT
Original Publish Date:	May 29, 2019
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=97218

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.