



# Aviation Investigation Final Report

---

<b>Location:</b>	Bolivar, Missouri	<b>Accident Number:</b>	CEN18FA186
<b>Date &amp; Time:</b>	May 22, 2018, 09:30 Local	<b>Registration:</b>	N622DP
<b>Aircraft:</b>	James Donald Baker Zenith	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>	Loss of control in flight	<b>Injuries:</b>	1 Fatal
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The private pilot departed for a local personal flight in the experimental airplane that he had built and flown for about 500 hours. A witness saw the airplane flying about 50 feet above trees with the nose oscillating up and down. According to the witness, the engine was not "making any strange noises [and had a] steady tone." The airplane struck trees and impacted the ground about 0.75 mile south of the airport.

Postaccident examination of the airframe, engine, and propeller revealed no discrepancies or anomalies that would have prevented normal operation. The damage to the propeller blades was consistent with rotation at impact. An autopsy of the pilot was not performed. According to the toxicology report, no ethanol or drugs were detected. Given the oscillations described by the witness, it is likely that the pilot did not maintain airplane control following the takeoff.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain airplane control after takeoff.

## Findings

---

<b>Personnel issues</b>	Aircraft control - Pilot
<b>Aircraft</b>	Pitch control - Not attained/maintained
<b>Environmental issues</b>	Tree(s) - Contributed to outcome

## Factual Information

### History of Flight

<b>Initial climb</b>	Loss of control in flight (Defining event)
<b>Uncontrolled descent</b>	Collision with terr/obj (non-CFIT)

On May 22, 2018, about 0930 central daylight time, an experimental amateur-built Zenith 601, N622DP, collided with trees and impacted terrain after takeoff from Bolivar Municipal Airport (M17), Bolivar, Missouri. The private pilot was fatally injured, and the airplane was destroyed. The airplane was owned by the pilot who operated it under the provisions of Title 14 *Code of Federal Regulations* Part 91 as a personal flight. Visual meteorological conditions were reported, and no flight plan had been filed. The local personal flight originated about 0925.

According to one witness, the airplane was flying "low above the trees," and the nose "going up and down about 50 feet above the trees." The witness reported that the engine wasn't "making any strange noises [and had a] steady tone."

The accident site was located about 0.75 mile south of M17 between the 16th and 18th holes at the Silo Ridge Golf and Country Club.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	87, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	3-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	BasicMed	<b>Last FAA Medical Exam:</b>	May 3, 2017
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	1662 hours (Total, all aircraft), 507 hours (Total, this make and model)		

The 87-year-old pilot held a private pilot certificate with an airplane single-engine land rating. He held a BasicMed certificate. The pilot reported having about 1,662 hours of flight experience of which about 507 hours were in the Zenith 601. The pilot also held three repairman experimental aircraft builder certificates.

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	James Donald Baker	<b>Registration:</b>	N622DP
<b>Model/Series:</b>	Zenith 601	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2007	<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental light sport (Special)	<b>Serial Number:</b>	6-3960-B
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	Condition	<b>Certified Max Gross Wt.:</b>	1200 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	506 Hrs	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>		<b>Engine Model/Series:</b>	C85-12
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	85 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

The airplane was constructed by the pilot from a kit and was issued a Federal Aviation Administration (FAA) certificate of airworthiness on June 21, 2007. It was powered by a Continental C85-12 engine, serial number 26363-6-12, rated at 85 horsepower, driving a Sensenich 2-blade, fixed pitch, wooden propeller, model number 68X54R. The Hobbs meter on the instrument panel indicated 506.5 hours.

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	SGF, 1268 ft msl	<b>Distance from Accident Site:</b>	22 Nautical Miles
<b>Observation Time:</b>	09:30 Local	<b>Direction from Accident Site:</b>	180°
<b>Lowest Cloud Condition:</b>		<b>Visibility:</b>	85 miles
<b>Lowest Ceiling:</b>	Broken / 400 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>		<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	30.07 inches Hg	<b>Temperature/Dew Point:</b>	22°C / 21°C
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Bolivar, MO (M17)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Bolivar, MO (M17)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	09:25 Local	<b>Type of Airspace:</b>	Class G

At 0930, the reported weather at the Springfield-Branson National Airport (SGF), Springfield, Missouri,

located about 21 miles south of the accident site, was wind, calm, visibility, 85 miles, ceiling, 400 feet broken; temperature, 22°C., dew point, 21°C., and altimeter setting, 30.08 inches of mercury.

## Airport Information

<b>Airport:</b>	Bolivar Municipal M17	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	1092 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	18	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	4000 ft / 75 ft	<b>VFR Approach/Landing:</b>	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Fatal	<b>Latitude, Longitude:</b>	37.600051,-93.409278(est)

Examination of the accident site revealed evidence consistent with the airplane striking the tops of trees on a magnetic heading of about 140°; descending in a nose-down attitude, and impacting terrain. The horizontal stabilizer was twisted 180° and displayed evidence of tree strikes. The leading edge of the right wing displayed numerous indentations consistent with tree strikes. A tree branch was embedded in the right main landing gear wheel pant. Broken tree branches lay scattered on the ground around the airplane. Flight control continuity was confirmed, and the shattered wooden propeller displayed evidence consistent with rotation at impact.

## Medical and Pathological Information

An autopsy of the pilot was not performed. The pilot's death certificate listed the cause of death as blunt force trauma. FAA's Bioaeronautical Science Research Laboratory, Oklahoma City, Oklahoma, performed toxicology testing, and no ethanol or drugs were detected. Cyanide and carbon monoxide testing were no performed.

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Scott, Arnold
<b>Additional Participating Persons:</b>	ROD McLAUGHLIN; FAA FLIGHT STANDARDS DISTRICT OFFICE; KANSAS CITY, MO MARC GIBSON; FAA FLIGHT STANDARDS DISTRICT OFFICE; KANSAS CITY, MO RUSTY KNOX; FAA FLIGHT STANDARDS DISTRICT OFFICE; KANSAS CITY, MO
<b>Original Publish Date:</b>	May 29, 2019
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=97300">https://data.nts.gov/Docket?ProjectID=97300</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).