



# Aviation Investigation Final Report

---

<b>Location:</b>	Myerstown, Pennsylvania	<b>Accident Number:</b>	ERA19LA061
<b>Date &amp; Time:</b>	December 8, 2018, 13:14 Local	<b>Registration:</b>	N731LT
<b>Aircraft:</b>	Cessna P210	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel related	<b>Injuries:</b>	1 Serious
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The pilot was flying the airplane to a nearby airport to obtain fuel. Before departing on the flight, he checked the fuel quantity using the onboard fuel totalizer and determined that both fuel gauges indicated adequate fuel for the intended flight. During the landing approach at the destination, the engine lost total power and the airplane impacted terrain short of the runway. The pilot reported that the loss of power was due to fuel starvation. A witness at the airport reported that the airplane made a "very sharp left-banking turn" as it flew overhead, then climbed steeply and made another sharp left turn to enter the traffic pattern for landing.

Examination of the airplane revealed no anomalies with the flight control system that would have prevented normal operation. No evidence of fuel was found in the engine-driven fuel pump filter; the filter was clean. There was no evidence of fuel in the lines between the engine-driven pump and engine gas producer. Before recovery from the accident site, less than 1 gallon of fuel was drained from the left wing tanks and less than 4 gallons of fuel was drained from the right wing fuel tanks.

The pilot's operating handbook for the airplane stated that, when the fuel tanks were 1/4-full or less, prolonged uncoordinated flight, such as slips or skids, could uncover the fuel tank outlets, causing fuel starvation and engine stoppage. It is likely that given the airplane's low fuel state, the abrupt maneuvers caused the fuel outlets to become uncovered, resulting in fuel starvation to the engine and a total loss of engine power.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to fuel starvation.

## Findings

<b>Aircraft</b>	Fuel - Fluid management
<b>Personnel issues</b>	Fuel planning - Pilot

## Factual Information

### History of Flight

Approach-VFR pattern final	Fuel related (Defining event)
Approach-VFR pattern final	Loss of control in flight

On December 8, 2018, at 1314 eastern standard time, a Cessna P210, N731LT, sustained substantial damage when it was involved in an accident near Myerstown, Pennsylvania. The private pilot was seriously injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot reported that he was flying to a nearby airport to refuel the airplane. He stated that he checked the fuel using the onboard fuel totalizer, and both fuel gauges indicated that there was enough fuel for the intended flight. During the approach, the engine lost total power on the downwind leg of the airport traffic pattern. The pilot reported that the loss of engine power was due to fuel starvation. The pilot also reported that he should have used a fuel tank dip stick to confirm the amount of fuel onboard.

According to a witness at the airport, as the airplane approached the airport, it made a "very sharp left-banking turn" as it flew over. The airplane then climbed steeply and made another sharp left turn to enter the left downwind for runway 19. He watched as the airplane continued the downwind leg, then made another sharp left turn to final. The airplane then turned to final and appeared to "stall" before impacting the ground. The airplane came to rest about one-half mile short of runway 19.

A review of photographs provided by a Federal Aviation Administration inspector revealed substantial damage to both left and right outboard wing sections. The engine was partially attached to the firewall and remained within the engine mount. Before recovery from the site, less than 1 gallon of fuel was drained from the left-wing tanks and less than 4 gallons of fuel was drained from the right-wing tanks. The fuel was examined for contamination, and none was found.

Examination of the fuel system revealed no evidence of fuel in the engine-driven fuel pump filter, and the filter was clean. There was no evidence of fuel in the lines between the engine-driven pump and engine gas producer.

The pilot's operating handbook for the airplane contained the note:

*Unusable fuel is at a minimum due to the design of the fuel system. However, when the fuel tanks are 1/4 full or less, prolonged uncoordinated flight such as slips or skids can uncover the fuel tank outlets, causing fuel starvation and engine stoppage. Therefore, with low fuel reserves, do not allow the airplane to remain in uncoordinated flight for periods in excess of one minute.*

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	69, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	3-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	July 3, 2017
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	(Estimated) 4500 hours (Total, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N731LT
<b>Model/Series:</b>	P210 N	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1979	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	P21000436
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	February 20, 2018 Annual	<b>Certified Max Gross Wt.:</b>	2303 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Turbo shaft
<b>Airframe Total Time:</b>	5076 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Allison
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	250-B17F2
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	250 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KMUI,487 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	13:56 Local	<b>Direction from Accident Site:</b>	10°
<b>Lowest Cloud Condition:</b>	Few / 3100 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Overcast / 4400 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>		<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.45 inches Hg	<b>Temperature/Dew Point:</b>	-7°C / -10°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Smoketown, PA (S37 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Myerstown, PA (9D4 )	<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>		<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	Deck 9D4	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	523 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	19	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3786 ft / 50 ft	<b>VFR Approach/Landing:</b>	Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious	<b>Latitude, Longitude:</b>	40.352222,-76.329719(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Alleyne, Eric
<b>Additional Participating Persons:</b>	Gary G Martin; FAA/FSDO; Harrisburg, PA Henry J Soderlund; Textron Aviation ; Wichita, KS Jack Johnson; Rolls Royce; Indianapolis, IN
<b>Original Publish Date:</b>	March 16, 2022
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=98745">https://data.nts.gov/Docket?ProjectID=98745</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).