



Aviation Investigation Final Report

Location: Bethel, Alaska Accident Number: GAA19CA239

Date & Time: May 1, 2019, 20:18 Local Registration: N524AV

Aircraft: Gippsland GA8 Aircraft Damage: Substantial

Defining Event: Ground collision **Injuries:** 7 None

Flight Conducted Under: Part 135: Air taxi & commuter - Scheduled

Analysis

The pilot reported that, while taxiing to the tie-down area after landing, during a "tight" right turn, the airplane's left wingtip struck a shipping container.

The airplane sustained substantial damage to the left-wing spar.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain adequate clearance from a shipping container while taxiing.

Findings

Personnel issues	Monitoring environment - Pilot
Environmental issues	(general) - Effect on operation

Factual Information

History of Flight

Taxi-from runway	Collision with terr/obj (non-CFIT)
Taxi-from runway	Ground collision (Defining event)

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	24,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	April 11, 2019
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 27, 2019
Flight Time:	(Estimated) 783 hours (Total, all aircraft), 129 hours (Total, this make and model), 733 hours (Pilot In Command, all aircraft), 123 hours (Last 90 days, all aircraft), 63 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Gippsland	Registration:	N524AV
Model/Series:	GA8 Undesignat	Aircraft Category:	Airplane
Year of Manufacture:	2015	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	GA8-15-214
Landing Gear Type:	Tricycle	Seats:	7
Date/Type of Last Inspection:	April 15, 2019 AAIP	Certified Max Gross Wt.:	4000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	4437 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	IO-540-K1A5
Registered Owner:	Global Air Concepts Llc	Rated Power:	300 Horsepower
Operator:	Global Air Concepts Llc	Operating Certificate(s) Held:	On-demand air taxi (135)

Page 2 of 4 GAA19CA239

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PABE,102 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	03:53 Local	Direction from Accident Site:	32°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 3900 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.94 inches Hg	Temperature/Dew Point:	9°C / 5°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Tuntutuliak, AK (A61)	Type of Flight Plan Filed:	Company VFR
Destination:	Bethel, AK (BET)	Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class D

Airport Information

Airport:	Bethel BET	Runway Surface Type:	Asphalt
Airport Elevation:	128 ft msl	Runway Surface Condition:	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	6 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	7 None	Latitude, Longitude:	60.77861,-161.837219(est)

Page 3 of 4 GAA19CA239

Administrative Information

Investigator In Charge (IIC):	Nepomuceno, Eleazar
Additional Participating Persons:	Hugh Youngers; FAA; Anchorage, AK
Original Publish Date:	March 3, 2020
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=99361

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 GAA19CA239