



# Aviation Investigation Final Report

---

<b>Location:</b>	Hope, Alaska	<b>Accident Number:</b>	ANC19LA027
<b>Date &amp; Time:</b>	June 11, 2019, 22:30 Local	<b>Registration:</b>	N10CJ
<b>Aircraft:</b>	Helio H391	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (partial)	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The pilot was conducting a local flight when the engine started to surge and run rough. He attempted to troubleshoot the problem, but was not able to restore engine power and located a precautionary landing site at an abandoned airstrip. During the landing roll, the airplane drifted right, and the right wing impacted vegetation, which resulted in a ground loop and substantial damage to the airplane.

A postaccident examination of the engine, airframe, and propeller revealed no anomalies that would have precluded normal operation, and the reason for the partial loss of engine power could not be determined.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during a precautionary landing, which resulted in a ground loop. Contributing to the accident was a partial loss of engine power for reasons that could not be determined.

## Findings

---

<b>Personnel issues</b>	Aircraft control - Pilot
<b>Aircraft</b>	Directional control - Not attained/maintained
<b>Aircraft</b>	Powerplant parameters - Unknown/Not determined
<b>Environmental issues</b>	Runway/landing area condition - Contributed to outcome

## Factual Information

### History of Flight

<b>Enroute-cruise</b>	Loss of engine power (partial) (Defining event)
<b>Landing-landing roll</b>	Loss of control on ground
<b>Landing-landing roll</b>	Collision with terr/obj (non-CFIT)

On June 11, 2019, about 2230 Alaska daylight time, a Helio H-391B airplane, N10CJ, sustained substantial damage when it was involved in an accident near Hope, Alaska. The private pilot and pilot-rated passenger were uninjured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot stated that, while flying over a natural gas pipeline, the engine started to surge and run rough, and the engine manifold pressure decreased. He cycled the throttle lever, increased the mixture lever to full rich, and turned on the electric fuel boost pump, but full power was not restored. The pilot-rated passenger pulled the carburetor heat lever out (carburetor heat on) with no effect on engine performance. The pilot was able to maintain altitude, but engine power was limited, so he searched for a precautionary landing site. He located an abandoned airstrip along the pipeline road and performed an approach to the north. The pilot reported that during the approach, he reduced power too late, which resulted in an overshoot of the best landing area, and that the airplane drifted right during the landing. During the landing roll, the right wingtip impacted vegetation, and the airplane ground looped and impacted trees, resulting in substantial damage to the left aileron and both sides of the stabilator.

The pilot stated that the engine surged slightly during the takeoff before the accident, but not enough to concern him. About two months before the accident, the airplane experienced a surge and partial loss of power during takeoff. A mechanic inspected the engine and conducted compression tests with no anomalies noted.

After the accident, the engine was intact and attached to the airframe with all fuel, oil, ignition and air lines secure. A fuel sample drained from the gascolator contained no contamination and was consistent with aviation fuel. The fuel filter was clear of debris. Continuity of the engine and the flight control system was established. The propeller blades were secure in the hub with no oil leaks observed. The engine started and accelerated smoothly and the propeller control cycled three times with corresponding change in manifold pressure, rpm, and oil pressure. The rpm was advanced to a maximum of 3,400 rpm for 5 seconds with no surges noted.

The propeller governor (Hartzell B-3) was removed and bench-tested at a Hartzell facility with no anomalies noted.

There was no evidence of any preexisting engine, propeller, or airframe discrepancies that would have precluded normal operation.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	65, Male
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	BasicMed With waivers/limitations	<b>Last FAA Medical Exam:</b>	May 6, 2019
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	1628 hours (Total, all aircraft), 225 hours (Total, this make and model), 1628 hours (Pilot In Command, all aircraft), 22 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Pilot-rated passenger Information

<b>Certificate:</b>	Private	<b>Age:</b>	54, Female
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>		<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>		<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	December 14, 2015
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Helio	<b>Registration:</b>	N10CJ
<b>Model/Series:</b>	H391 B	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1958	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	099
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	December 21, 2018 Annual	<b>Certified Max Gross Wt.:</b>	3000 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	4481 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	GO-435-C2B2-6
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	260 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	PANC,132 ft msl	<b>Distance from Accident Site:</b>	21 Nautical Miles
<b>Observation Time:</b>	05:53 Local	<b>Direction from Accident Site:</b>	358°
<b>Lowest Cloud Condition:</b>	Few / 5500 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Broken / 25000 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	16 knots / 27 knots	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	150°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.79 inches Hg	<b>Temperature/Dew Point:</b>	17°C / 7°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Nikishka, AK (AK73)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Nikishka, AK (AK73)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	21:00 Local	<b>Type of Airspace:</b>	Class G

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	60.811943,-150.00666(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Price, Noreen
<b>Additional Participating Persons:</b>	David Longan; Federal Aviation Administration; Juneau, AK
<b>Original Publish Date:</b>	July 15, 2021
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=99700">https://data.ntsb.gov/Docket?ProjectID=99700</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).