







**Aircraft Category:** 



Helicopter



# Aviation Investigation Preliminary Report

Location: Albany, TX Accident Number: CEN21LA109

Date & Time:January 9, 2021, 10:00 LocalRegistration:N322SHAircraft:ROBINSON HELICOPTER R44 IIInjuries:3 None

Flight Conducted Under: Part 91: General aviation - Other work use

## **Aircraft and Owner/Operator Information**

Aircraft Make: ROBINSON HELICOPTER Registration: N322SH

Model/Series: R44 ||
Amateur Built:

Operator: S2 HELICOPTER SERVICES Operating Certificate(s) None

LLC Held:

**Operator Designator Code:** 

#### **Meteorological Information and Flight Plan**

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	GZN,1711 ft msl	Observation Time:	10:20 Local
Distance from Accident Site:	25 Nautical Miles	Temperature/Dew Point:	2°C /2°C
<b>Lowest Cloud Condition:</b>	Clear	Wind Speed/Gusts, Direction:	3 knots / , 150°
Lowest Ceiling:	None	Visibility:	7 miles
Altimeter Setting:	30.34 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Albany, TX	Destination:	Albany, TX

### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	32.729096,-99.271909 (est)

# Administrative Information

Investigator In Charge (IIC):	Link, Samantha
Additional Participating Persons:	Corey Wehmeyer; FAA FSDO; Lubbock, TX Troy Helgeson; Lycoming Engines; Williamsport, PA Thom Webster; Robinson Helicopter Company; Torrance, CA
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 CEN21LA109