













Aviation Investigation Preliminary Report

Location: Molalla, OR Accident Number: WPR22LA034

Date & Time: November 15, 2021, 08:19 Local Registration: N103WC

Aircraft: Bell OH-58A Injuries: 1 None

Flight Conducted Under: Part 133: Rotorcraft ext. load

Aircraft and Owner/Operator Information

Aircraft Make: Bell Registration: N103WC

Model/Series: OH-58A Aircraft Category: Helicopter

Amateur Built:

Operator: EDGEFIELD AVIATION LLC **Operating Certificate(s)** Rotorcraft external load

Held: (133), Agricultural aircraft

(137)

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KUAO,196 ft msl	Observation Time:	07:53 Local
Distance from Accident Site:	10 Nautical Miles	Temperature/Dew Point:	14°C /10°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	11 knots / 18 knots, 190°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	29.86 inches Hg	Type of Flight Plan Filed:	CVFR
Departure Point:	Sandy , OR	Destination:	Molalla, OR

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	45.147285,-122.57571 (est)

Administrative Information

Investigator In Charge (IIC): Nepomuceno, Eleazar

Additional Participating Persons: Erik Ramseyer; FAA; Hillsboro, OR

Investigation Class: Class 3

Note: The NTSB did not travel to the scene of this accident.

Page 2 of 2 WPR22LA034