



PORT STATE CONTROL PREVENTIVE ASSESSMENT

File No. 16/XA/695/01

RINA No. 76747

Ship's Name CARIBBEAN FANTASY

This is to confirm that the topics addressed by the PSC Deficiency Cards associated with the class and/or statutory surveys presently carried out (see below) were duly reviewed, checked on board and:

- no deficiencies were found;
- deficiencies were found.

Notes:

- numbering of topics is the same of PSC Deficiency Cards
- in case of class and/or statutory surveys partially held, the numbers of topics remaining to be checked are to be listed in the Narrative section
- deficiencies found for the topics, if any, are to be reported in the Narrative section
- for each topic, at least two significant pictures have always to be attached in the Pictures section
- all topics are always to be checked when an Unscheduled Survey is carried out

Topics associated to statutory surveys relevant to SAFEQU or SAFPAS certificates:



1. Fire dampers (engine room)
2. Main fire pumps
3. Emergency fire pump
4. Fire main
5. Quick closing devices
6. Emergency stops
7. Emergency source of electrical power
10. Lifeboats
11. Life rafts
12. Launching appliances
14. Outfitting and cleanliness of engine room and steering gear room
15. Nautical charts and publications
18. On-load off-load lifeboat release gear
19. Ship certificates and document, officers ratings certification
21. Fixed pressure water spray system for special category space (where fitted)

Topics associated to class and/or statutory surveys relevant to certificates other than SAFEQU or SAFPAS:



7. Emergency source of electrical power
8. Oil filtering equipment
9. Sludge tank (illegal overboard connections)
13. Load line appliances
14. Outfitting and cleanliness of engine room and steering gear room
16. Leakage from sloping plate of top side ballast tanks (where fitted)
17. Main deck, exposed decks and superstructures
19. Ship certificates and document, officers ratings certification
20. Stern doors (where fitted)

Port of Survey: GIBRALTAR

Date of Survey: 14/07/2016



RINA Surveyor name and signature



RINA Marine Manager name and signature

Narrative section

At Owner's request the vessel has been attended at Gibraltar, in order to perform PSC follow-up inspection. Vessel was detained on the 08/07/2016 because the 3 auxiliary engines were not working, and vessel was under emergency generator.

During follow-up survey, D/G no.1 and D/G no.2 have been subjected to a dedicated berth trial, including alarms and safety devices, with satisfactory results.

Cleanliness of engine room has been improved during the inspection and found in satisfactory condition.

Sea water feed pump has been satisfactorily tested and it is now working properly

The following deficiencies have been found:

- 1) D/G no.3 to be considered out of service due to damage. Recommendation will be issued accordingly.
- 2) Minor oil leakage from D/G no.1 and from D/G no2 have been detected. Some additional water leakage have been detected. A Recommendation will be issued accordingly.

Pictures section

1 Fire dampers (engine room)

Pictures (attach at least 2 significant shots for each subject)

2 Main fire pumps



Pictures (attach at least 2 significant shots for each subject)

3 Emergency fire pump



Pictures (attach at least 2 significant shots for each subject)

4 Fire main

na

Pictures (attach at least 2 significant shots for each subject)

5 Quick closing devices



Pictures (attach at least 2 significant shots for each subject)

6	Emergency stops
<div style="display: flex; justify-content: space-around;"> <div style="width: 45%;"> </div> <div style="width: 45%;"> </div> </div>	

Pictures (attach at least 2 significant shots for each subject)

7	Emergency source of electrical power
na	
Pictures (attach at least 2 significant shots for each subject)	

8	Oil filtering equipment
<div style="display: flex; justify-content: space-around;"> <div style="width: 45%;"> </div> <div style="width: 45%;"> </div> </div>	

Pictures (attach at least 2 significant shots for each subject)

9	Sludge tank (illegal overboard connections)
na	
Pictures (attach at least 2 significant shots for each subject)	

10	Lifeboats
Na	
Pictures (attach at least 2 significant shots for each subject)	

11	Liferafts
na	
Pictures (attach at least 2 significant shots for each subject)	

12	Launching appliances
na	
Pictures (attach at least 2 significant shots for each subject)	

13	Load Line appliances
na	
Pictures (attach at least 2 significant shots for each subject)	

14	Outfitting and Cleanliness of engine room and steering gear room
----	--



Pictures (attach at least 2 significant shots for each subject)

15	Nautical charts and publications
na	
Pictures (attach at least 2 significant shots for each subject)	

16	Leakage from sloping plate of top side ballast tanks
na	
Pictures (attach at least 2 significant shots for each subject)	


17	Mai deck, exposed decks and superstructures
	
Pictures (attach at least 2 significant shots for each subject)	

18	On-load Off-load lifeboats release gear
na	
Pictures (attach at least 2 significant shots for each subject)	

19	Ship certificates and document, officers and rating certification
na	
Pictures (attach at least 2 significant shots for each subject)	

20	Stern doors
na	
Pictures (attach at least 2 significant shots for each subject)	

21	Fixed pressure water spray system for special category space
na	
Pictures (attach at least 2 significant shots for each subject)	

22	Purifier room
	
Pictures (attach at least 2 significant shots for each subject)	