
* SSM

DISTRESS INFO

1-OCT-2015 11:13:20

Distress Alert received and being processed

Distress Alert has been received and is being processed

from mobile (return id):

Message:

----- Distress Alert Received -----

Mobile Terminal No : 436820812

To CES : 001

Position : 23.28'N 73.48'W

Position updated : 10:30 UTC Nature of distress : Flooding

Course : 235 Speed : 8

Activation : Distress Alert

Position activated : Yes Course/Speed updated : Yes

DESCRIPTION:

A distress alert message has been received from the mobile. The message will be stored and forwarded to the MRCC address.

ACTION BY SYSTEM:

The message will be forwarded to the MRCC destination.ACTION BY OPERATOR: The operator should supervise the correct delivery of the distress alert message.

*

MHM DISTRESS ALARM 1-OCT-2015 11:13:21

Ship originated distress message received and being processed

Ref:910348/0 From:436820812 To: Data

----- Distress Alert Received -----Mobile Terminal No : 436820812

To CES : 001

Position : 23.28'N 73.48'W

Position updated : 10:30 UTC
Nature of distress : Flooding

Course : 235 Speed : 8

Activation : Distress Alert

Position activated : Yes Course/Speed updated : Yes

DESCRIPTION:		
A distress message has been	received from a ship.	
ACTION BY SYSTEM: Message will be forwarded to be set off when the message		m will
ACTION BY OPERATOR: No action delivery.	n for operator, except to s	upervise the correct
**********	*********	*******
МНМ		1-OCT-2015 11:13:22
• • • • • • • • • • • • • • • • • • • •		
Ship originated distress messa	age received and being proc	essed
Ref:910348/0 From:436820812 To	:	
*********	*********	******
* MHM		1-OCT-2015 11:13:23
Ship originated distress messa	age has been delivered	
Ref:910348/0 From:436820812 To	:	
DESCRIPTION: A Ship originated distress resuccessfully delivered.	message has been	
ACTION BY SYSTEM: No further action.		
ACTION BY OPERATOR: No action		