

HMS BOUNTY - IN WATER SURVEY

Oct 19, 2012

D. Wyman

Oct 19, 2012

0800-1200

Attending - Capt Robin Walbridge, Ch Mate John Jones

Owner (new address) HMS Bounty Organization LLC, 22 Research Way  
East Setauket, NY 11733

Vessel Moored to pier at Boothbay Harbor Shipyard, Boothbay Harbor, ME

Entered and inspected all Compartments -

Forepeak - Good Condition, Ventilation with small exhaust duct - good

Sewage Rm - Poor Ventilation, otherwise OK

Fwd Crew Berthing - Good

Bosun Stores - Good

Aft Crew Berthing - Crew berths being installed, new watertight  
hd completed between Tank Rm + Berthing  
Good Condition

Tank Rm - Note Tank room and crew berthing spaces were  
switched locations to get Tank room next to Engine Rm -  
New Stainless Steel Fuel Tanks (2) installed, (2) existing  
stainless steel water tanks converted to Fuel and  
(2) new poly water tanks installed. Work nearing  
completion at time of survey.

Engine Room - Good

Officer Berthing Aft - Good

Tween Deck - Good

Main Deck - Good except steering tiller of steel found significantly  
corroded and weakened, recommended repair which  
was begun at time of survey

The vessel was found in good condition. She had just completed  
a haul out and painting at bottom prior to my survey.  
Captain reported bottom was in good condition.

Recommendations -

(1) Repair Tiller where significantly corroded by adding a  
new reinforced Top plate

(2) Better Ventilation for all hold spaces should be provided.