



Photo 1 – View of damaged canopy and empennage (Photo courtesy unknown)