



Photo 1 – View of damaged right wing and empennage (Photo courtesy of the pilot)