



Photo 1 – View of damaged tail rotor blade (Photo courtesy of the operator)