



Photo 1 – View of damaged empennage and right-wing lift strut (courtesy of the FAA)