

Photo 1 – Google Earth image of where the wood power line pole was impacted and where the airplane came to rest (courtesy of the Federal Aviation Administration).



Photo 2 – View of the airplane after it came to rest (courtesy of the Federal Aviation Administration).



Photo 3 – View of the airplane after it came to rest (courtesy of the Federal Aviation Administration).



Photo 4 – View of the damage to one of the metal propeller blades (courtesy of the Federal Aviation Administration).



Photo 5 – View of the wood power line pole in the field (courtesy of the Federal Aviation Administration).



Photo 6 – View of the metal bracket that was mounted on top of the wood power line pole (courtesy of the Federal Aviation Administration).




Photo 7 – SunCalc.org image of the accident site showing the altitude and azimuth of the sun at the time of the accident (courtesy of SunCalc.org)