



Photograph 1 – Aerial View of Accident Site (Courtesy of Montana Department of Aeronautics)



Photograph 2 – View of Accident Site from Canyon



Photograph 3 – View of Initial Impact Point



Photograph 4 – Close-up View of Initial Impact Point



Photograph 5 – View of Main Wreckage and Left Wing from Upper Initial Impact Point (Courtesy of Textron Aviation)



Photograph 6 – View of the Left Wing



Photograph 7 – View of Right Wing (Courtesy of Textron Aviation)



Photo 8 – View of Engine at Accident Site



Photo 9 – View of Disassembled Vacuum Pump



Photo 10 – View of Attitude Indicator