



Photo 1 – View of Accident Site from Initial Impact Point



Photo 2 – View of Intermediate Ground Scar at Accident Site



Photo 3 – View of Main Wreckage from the East



Photo 4 – View of Main Wreckage from the West



Photo 5 –Vacuum Driven Instruments Recovered from Accident Site



Photo 6 – Photograph of Tachometer Recovered from Accident Site



Photo 7 – Photograph of Rotor and Carbon Vanes