



Photo 1 –View of main wreckage



Photo 2 – View of engine assembly



Photo 3 – View of tail boom in tree at wreckage site



Photo 4 – View of tail boom vertical fins and rotor blades in tree



Photo 5 – View of engine fan



Photo 6 –View of main rotor mast



Photo 7 –View of tail rotor gear box



Photo 8 – View of main rotor swash plate and main rotor head



Photo 9 – View of fragments of recovered cockpit



Photo 10 – View of recovered tail boom



Photo 11 – View of main rotor head and blades




Photo 12 – View of main rotor head and swash plate



Photo 13 –View of belt drive



Photo 14 – View of right side of engine



Photo 15 – View of front of engine with drive assembly



Photo 16 –View of left side of engine



Photo 17 – View of accessory section of engine



Photo 18 –View of bottom of engine showing engine sump



Photo 19 – View of main rotor head/swash plate with missing pitch control linkage



Photo 20 –View of accident site