



**Photo 1 – View of damaged right wing ribs (photo courtesy of the FAA)**



**Photo 2 – View of fuel remaining in fuel tanks (photo courtesy of the FAA)**