



Photo 1 – View of Fuselage and Tail from the Southwest with Wings in the Foreground



Photo 2 – Fuselage and Tail with Wing Section in Foreground



Photo 3 – View of Tree Strikes and Initial Impact Point



Photo 4 – View of Main Wreckage from Tail



Photo 5 – View of Engine and Propeller on Examination Table



Photo 6 – 2-bladed Propeller at Examination Facility