



Photo 1 – View of damaged left wing lift strut (Photo courtesy of Airport Supervisor)



Photo 2 – View of damaged rudder (Photo courtesy of the Airport Supervisor)