



Photo 1 – View of damaged right wing lift strut and fuselage (Photo courtesy of insurance adjuster)



Photo 2 – View of damaged rudder (Photo courtesy of the insurance adjuster)