



Photo 1 - Front view of inverted airplane (photo courtesy of the pilot)



Photo 2 - View of left wing lift strut damage (photo courtesy of the pilot)