



Photo 1 – View of damage to left-wing lift strut (courtesy of the FAA)



Photo 2 – View of damage to empennage (courtesy of the FAA)