



Photo 1 – View of helicopter in grass adjacent taxiway (photo courtesy of the FAA)



Photo 2 - View of left-hand anti-vibrator mount beam damage (photo courtesy of the FAA)