



**Photo 1 – View of damaged empennage (Photo courtesy of the airport manager)**