



**Photo 1 –View and location of accident site showing surrounding tree impact damage.**



**Photo 2 –View of fuselage damage looking aft towards tail.**



**Photo 3 – Left engine, propeller and wing damage. The entire assembly is upside down.**



**Photo 4 –Close up view of left propeller and engine damage.**



**Photo 5 -Right propeller hub separated from engine. All blades remained attached.**



**Photo 6 -Right profile view of fuselage and tail.**