



Photo 1 – View of main wreckage from rooftop of adjacent building



Photo 2 – View of main wreckage 1



Photo 3 – View of main wreckage 2



Photo 4 – Panoramic view of accident site from main impact crater after wreckage recovery (Honeywell Photograph)



Photo 5 – View of recovered wreckage on trailer 1



Photo 6 – View of recovered wreckage on trailer 2



Photo 7 – View of left engine after recovery from the accident site



Photo 8 – View of right engine after recovery from accident site



Photo 9 – Left engine propeller blades



Photo 10 – Right engine propeller blades



Photo 11 – Left and right engine compressor stages and compressor housings (Honeywell photograph)



Photo 12 – Left and right engine turbine rotor stages (Honeywell Photograph)