
- 1.) Performed Mini Inspection IAW Cessna Phase Card Inspection Program
- 2.) Replaced RH MLG Fairing Assy (PN-2641032-202)
- 3.) Replaced Bulb on Tail Light
- 4.) Inspected and Serviced Propeller with Aeroshell #6 Grease
- 5.) Replaced Oil Filter PN-05228-7513983 and Captured SOAP Sample


This AIRFRAME was inspected IAW Cessna's C-208 Caravan Phase Card Inspection Program and ICA Report No. 9004-21 and was determined to be AIRWORTHY in respect to the work completed. APPROVED FOR RETURN TO SERVICE



N7581F SN-208B0389 7-20-16 ACTT-10660.1 ACTC-22421 SN- P123146 TTSN-2396.1 TCSN-4641

- 1.) Performed Mini Inspection IAW Cessna Phase Card Inspection Program
- 2.) Replaced Oil Filter PN-05228-7513983 and Captured SOAP Sample

This ENGINE was inspected IAW Cessna's C-208 Caravan Phase Card Inspection Program and Honeywell Maintenance Manual and was determined to be AIRWORTHY in respect to the work completed. APPROVED FOR RETURN TO SERVICE



N7581F SN-208B0389 7-20-16 ACTT- 10660.1 ACTC-22421 SN- CDA5411 TTSN- 2396.1

- 1.) Performed Mini Inspection IAW Cessna Phase Card Inspection Program
- 2.) Inspected and Serviced Propeller with Aeroshell #6 Grease

This PROPELLER was inspected IAW Cessna's C-208 Caravan Phase Card Inspection Program and Hartzell Propeller Insp. Manual No. 139 and was determined to be AIRWORTHY in respect to the work completed. APPROVED FOR RETURN TO SERVICE

Mark A. Fields