National Transportation Safety Board

Office of Research and Engineering Washington, D.C. 20594

Performance Erratum

Specialist Report Marie Moler

A. EVENT SUMMARY

Location:	San Francisco, California
Date:	July 7, 2017
Time:	2356 PDT
Airplane:	Airbus A320, C-FKCK, ACA759
NTSB Number:	DCA17IA148

B. ERRATUM

In the Performance Study for DCA17IA148, the time for the tower ordering a go-around is written incorrectly in three places. The correct time for this event should be 23:56:09.

On page 13 the time in the second paragraph is listed as 23:56:10 when it should be 23:56:09. However, the position of the "Tower: go around" in Figure 13 on the page accurately reflects the time of 23:56:09. On page 16, in Table 1, the time for "Tower ordered go- around" should be 23:56:09. The distance and altitude measurement, however, accurately reflect what they were at 23:56:09. Finally, on page 17, the last sentence in the conclusion should say the tower ordered a go-around at 23:56:09 rather than 23:56:10.

Marie Moler Specialist – Airplane Performance National Transportation Safety Board