

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Western Pacific Region

AIRFRAME MAINTENANCE RECORDS EXCERPTS

NTSB Accident: WPR14FA132 Accident Date: March 8 or 9, 2014 (Actual date/time uncertain)

This document contains 3 embedded images

A. ACCIDENT

Location:	Near Carson City Nevada
Date:	Unknown
Aircraft:	Cessna 120, N76856, Serial # 11290
NTSB IIC:	Michael Huhn

B. EXAMINATION PARTICIPANTS:

Michael Huhn	Henry Soderlund
Air Safety Investigator	Air Safety Investigator
National Transportation Safety Board	Cessna Aircraft Company
Western Pacific Region	Wichita, KS.
Lee Oscar	Michael Becker
Maintenance Inspector	Manager
FAA FSDO	FAA FSDO
Reno, NV	Reno, NV

C. SUMMARY

On Sunday March 9 about 1500 Pacific daylight time the wreckage of an airplane was detected by a private citizen while he was flying over a mountainous region about 6 miles southeast of Carson City airport (CXP) Carson City, Nevada. Carson City Sheriff's Office was notified, and search and rescue (SAR) personnel arrived at the accident site by about1630 the same day. They reported the airplane tail number, and that there was 1 male individual on board, who was deceased.

The images of the maintenance records were obtained by an FAA inspector who visited the pilot's residence.

The records indicated that the most recent annual inspection was completed on June 2 2013, when the airplane had a TT of 5492.27 hours and an unspecified hour meter indicated 3599.66 hours.

D. EXCERPTED RECORDS

TACH OR RECORDING METER TIME DATE DESCRIPTION OF WORK PERFORMED-5463 JU TOTAL brought forward from previous pape 12/1/12 3562 3562.51 INSTRUED NEW FUEL SELECTER VALVE, PART # VO411716-500 LASTAUGO ASPER UNIVAIR REPORT 2316-3, LEV. A. VALUE TESTED FOR OPERATON AND SECURITY. NO LEAKS FOUND AIRCRAFT FOR RETURY TO SERVICE . VALVE ISA FAA/ PHA PART. G 2 2/11/13 5475.23 3579.62 Replaced Right Main Tire Airhaule 6 X6X6 JJ Micel: CP 6/2/13 5492.27 3599.66 I CERTITY THIS AIRCRAFT MAS BEEN INSPECTED IN ACCORDANCE WITH CESSNA 100 SERIES INSPECTING PROCEDURES AND FOUND TO BE IN ATRUSERT COMPTON. LUBOR ALL CONTOL HINGES, PURYS & LENGAGES ASNECESSARY. LEFT FUEL TANK FILER TIGHARD, TIGHNOO LEFT PLOT PLODGE PETH BOGT. CEANED AND REPAINDED ECENATER COURLING BEECON RUDDER. REPLACED RIGHT NAVE GLIHT BURB, TESPED ELT FOR SECURITY & FUNCTION ELT BATTER REPLACEMEN OUF B/14. SERVICED BRAKE MASTER CHINDLESS. SERVICED BRUERY. CONPLUED WITH ADY7-26-02 CEAD, NG EDGE, NOPEGRON, COMPLED WITH AD 47-43-04 RUDDER CONTROL CABLE HORN INSPECTION, CONTRUS WITH HO 47 43.05 ELENATER SPAR BY INSPECTOR, CONFILED WITH AD 47-50-02.87 INSPECTION, CONPLIED WITH AD 48-07-01 5745 WEE ATTACH BOOTS BY INSPECTORS CALAD 49-25-08 DRAG WIRES BY INSPECTOR CWAD 79-08 03 CIGAR LIGHER BY INSPECTOR COMPLETE LIST OF AD COMPLIANCE FOND UN ARCEAPSPINIONE RECOLDS - AIRERING NORE : THE SUB-TOTAL this page TOTAL-Carry forward to next page

Figure 1 - Most Recent Records Page

	JJ Micel. CP
	6/2/13 5492.27 3599.4
8	I CERTITY THIS AIRCRASS
	WITH CESSNA 100 SERIES INSPECTING PROCEEDING ACCORDANCE TO BE IN ATRUSATION CONDITION INDED DUE AND FOUND
	TO BE IN ARRIVER IN THE CHINY TROEEDURES AND FOURP
1-22	POULS ALENGAGES ASNESS ASNESS ASNESS TO CONTROL HINGES,
	MGREACED, TIGHTVED I FOR DUE DOWN OFFT FUEL THING FILER
	TIGHAND, TIGHNOO LEFT PLOT PLOT PLOT FUEL TANK FILER. AND REPAINDED ELEVATOR COURLING BELOW RUDDER. REPLACED RIGHT WAVE LIGHT BUT B. DECED ELEVANDER. REPLACED
	RIGHS WAVE LIGHT BUY & DECOR FUDDER. REPLACED
	ELT BATTER REPLACENEN OUF B/14, SERVICED BRAKE MASTER CHUNDERS.
	SERVICED BADERT. COMPLED WITH AD 47-26-02 CEARING EDGE INSPECTIONS. COMPLED WITH AD 47-43-0481000 200 200 CEARING EDGE INSPECTIONS
-	COMPLED WITH AD 47-43-04 RUDATE CONTROL CABLE HARN INSPECTION, COMPLETE WITH AD 47-43-05 ELEMAN SUDATE CONTROL CABLE HARN INSPECTION, COMPLETE WITH
1	AD 47-43-05 ELEVATER SPAR BY INSPECTION, COMPLED WITH AD 47-50-02 BY
14	INSPECTIONS CONPLIED WITH AD 48-07-01 57AB LITE ATTACH ABOUTS BY INSPECTIONS CALAD
	48-25-03 DRAG WIRES BY INSPECTIONS CW AD 79-08-03 CIGAR LIGHER BY INSPECTIONS
	COMPLETE LIST OF AD COMPLIANCE FOND ON ARCAM STMARE RECORDS - ARCENT
	APPROUSD TO REFURE TO SERVICE . Q.
	NOTE: TPX 24 NO CHECK OUTER UF DC
	TOTAL—Carry forward to next page
1	

Figure 2 - Most Recent Annual Inspection Entry

DATE	TOTAL	TACH OR RECORDING METER TIME	SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
Onre	SERVICE		oht forward from previous page	
Ħ		Cessna I Continental C-8 Senso Replaced dash ELT complies researched see	20 S/N: 11290 NC76856 Tach: 2466.66 TTIS: 5252.81 06/16/2011 5-12 S/N: 25936-6-12-6-12 Tach: 2466.66 TT: 5253.66 TSMOH: 1797.66 enich 76AK-2-44 S/N: 37949 Tach: 2466.66 TSMOH: 207.09 panel Lord Mounts. Replaced (1) cowl fastener. Replaced BA4108 air filter, with FAR 91.207 (d). Battery good until 03/12. A/D notes thru 2011-12 attached in addendum. hts aircraft has been inspected in accordance with an Annual Inspection was determined to be in an airworthy condition.	
03		1		
			A STANDARY CA EXCAUNTER	
-	Tach	011 Tach 2481 time now reads Hagler	2, total time 5267.35 Recording tachometer replaced with servicible used part.	
-				
02 comp with AD Complie hours: Fe required. with AD due at no miss. No due at no miss. No entificient complied v bearings an system with element Photo tage. Reven	slied with by 47-43-04 b d with AD 4 with AD 4 with AD 4 48-07-01 by t annual ins efects found (angles atta with by prop of tires. Rep htydraulic 1 BA4106.1 alled and tee T was tested	the presence of y inspection of 7-43-05 by in s 50-02 complied 48-05-04 compli- inspection of h pection. Compli- Next due 550 ched to vertical ched to vertical force faced all brake huid. Cleaned a Removed fuel s	TTAF. Removed covers and panels as necessary for inspection. sex, pulleys, cables and linkages as necessary. Found AD 47-26- frivets detectable beneath wing leading edge fabric. Complied nudder cable horns. No defects found. Next due 5506 hours. pection of elevator spar web. No defects found. Next due 5506 d with by presence of reinforcing doubler. No further action ined with by presence of placard on instrument panel. Complied orizontal stabilizer attaching hardware. No defects found. Next is dwith AD 48-25-03 by inspection of wing drag wires and 6 hours. Found AD 50-31-01 complied with by presence of 1 fin spar. No further action required. Found AD 79-08-03 ction to cigar lighter (fuse). Checked brakes, wheels, wheel pads. (PIN RA66-105) and resealed calipers. Serviced brake and greased tailwheel. Serviced gascolator. Replaced air filter hatoff valve. Disassembled and cleaned and replaced shaft O cked all lights. Replaced ELT battery P/N BP1010. (expires 1 fins. 2071 (d) and found to be satisfactory.	5406.83 3511.20 1895.63
	Contraction of the local division of the loc	has have in	A&	
Tom Hagler	-		cted in accordance with an annual inspection and was	
	F46.43		a Left Main Tire ETude Arband 6x Macel: CP	6.7.6 PLY
101	L-Carry	forward to	next page	

Figure 3 - Penultimate Annual Inspection Entry