



Airworthiness - Photo 11. Close-up view of the upper spar cap fitting of the wing carry-through section where it mates with the left wing spar. Note rearward direction of fractures. (NTSB-I12)