



Airworthiness - Photo 15. View of the damage to the bottom structure of the aft-facing passenger seats in row