



Airworthiness - Photo 24. View of all three propeller blades after removal from hub by investigators. Note "S" bending, chordwise scratching, and leading edge gouging. Also note two impressions in leading edge of blade no. 1 (denoted by arrow). (NTSB-CC)