



Airworthiness - Photo 25. Close-up view of leading edge damage of propeller blade no. 1. (NTSB-CC)