



Airworthiness - Photo 8. View of right wing damage (view from forward looking aft). Note that the entire length of the wing spar was recovered. (NTSB-C3)