



Photo 6: Close up of the R/H Control Tab Crank (clevis) Fitting. View looking aft.
Note the contact damage on the forward face of each clevis lug.